





report date: 2024-03-28

General information

Make	AUDI
Model	A3 TDI SPORT NAV
Colour	Black
Year of manufacture	2016
Top speed	124 mph
0 - 100 km/h	10.5 seconds
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	81 kW / 110 HP / 109 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	78.5 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-07-16
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	16
Total items failed	0

MOT #7	2023-07-17 09:57
MOT test number	715017654099
Result	✓ Passed
Next expiry date	2024-07-16

MOT #6	2022-07-11 07:59
MOT test number	427494748087
Result	√ Passed

MOT #5		2022-01-12 17:52
MOT test	number	525235667953
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT #4 2022-01-12 10:37

MOT test number 148743234332

Result X Failed

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

DANGEROUS Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #3 2021-01-14 13:14

MOT test number 956590157452

Result
✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #2 2021-01-13 13:28

MOT test number 337153144290

Result X Failed

MAJOR Offside Position lamp not working (4.2.1 (a) (ii))

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm 225/45/17 91h (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1 2019-03-29 15:08

MOT test number 545597153424

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	16 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

,	
For how long did the current and previous owner(s) have this AUDI? How many owners did check it in the premium report and see all owner registrations. Download the full report is	
THE STATE OF THE S	

THE PARTY OF THE P	

	More info >
	Piore inito
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Francis and Anti-	NE
Cornent region atom	OK SIE
Plate since	
Current registration	NK UK
Finds since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-03-09
Last registration	2023-07-17
Complete history	See info



Registration #1	2016-03-09	28 mi
Registration #2	2019-03-29	48.506 mi
Registration #3	2021-01-13	79.738 mi
Registration #4	2021-01-14	79.738 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Adult	95%
Children	87%
Pedestrian	74%
Safety systems	86%
Overall rating	88%
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1424 mm
Length	4241 mm
Wheel base	2601 mm
Kerb weight	1230 kg
Max. allowed weight	1790 kg

Additional information

		-
Fuel tank capacity	50 l	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number CXXB457979