





General information

Make	BMW
Model	X5 XDRIVE40D
Colour	Black
Year of manufacture	2013
Top speed	147 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	302 BHP	0 < 101
Max. torque	600 Nm at 1.500 rpm	101 - 120
Engine capacity	2.993 сс	121 - 140
Cylinders	6	141 - 165
Fuel type	Diesel	166 - 185
Consumption city	32.1 mpg	186 - 225
Consumption extra urban	41.5 mpg	225+
Consumption combined	37.7 mpg	
CO2 emission	198 g/km	
CO2 label	J	



MOT history

MOT expiry date	2025-04-24
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	19
Total items failed	11

MOT #13	2	2024-04-25 08:54
MOT test	number	918660334921
Result		✓ Passed
Next expi	ry date	2025-04-24
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Outer Drive shaft flexible coupling slightly deteriorated (6.1.7 (d) (i))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

2024-04-24 15:11 MOT #12 241262857854 **MOT test number** Result × Failed Fail Windscreen washer not working (3.5 (a)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Pass with rectification Headlamp aim too high both (4.1.2 (a)) Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Offside Front Outer Drive shaft flexible coupling slightly deteriorated (6.1.7 (d) (i)) Advice

MOT #11	2023-03-20 15:03
MOT test number	242605645930
Result	✓ Passed





MOT #10	2022-01-26 11:26
MOT test number	975688109524
Result	🗸 Passed
МОТ #9	2020-12-05 11:56
MOT test number	343090772669
Result	Passed
MOT #8	2020-11-16 10:47
MOT test number	372263829994
Result	🗙 Failed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Position lamp not working BOTH REARS (4.2.1 (a) (ii))	
FailBrake performance not tested (1.2.1 (g))	
Fail Tyre tread depth below requirements of 1.6mm BOTH FRONTS (5.2.3 (e))	
Fail Offside Front Drive shaft likely to become detached (6.1.7 (a) (ii))	
Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail Steering system fouling (2.1.4 (a))	

MOT #7	2019-10-01 11:36
MOT test number	831538847214
Result	✓ Passed
Minor Offside Rear Inner Position lamp with a multiple light source up to	0 1/2 not functioning (4.2.1 (a) (i))
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	





MOT #6	2019-09-23 14:41
MOT test number	377381347669
Result	🗙 Failed
Fail Nearside Suspension unit damaged or deteriorated and function affected not sea lower mount damaged and not aligned (5.3.5 (b) (i))	ated correctly and
Minor Offside Rear Inner Position lamp with a multiple light source up to 1/2 not func	tioning (4.2.1 (a) (i))
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice No n/s fog light working	
Fail Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))	
Minor Brake fluid warning lamp illuminated (1.1.10 (f))	

MOT #5		2018-09-28 08:05
MOT test	number	965941159858
Result		✓ Passed
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	

MOT #4	2018-09-27 10:09
MOT test number	834307875126
Result	🗙 Failed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #3	2017-09-27 13:07
MOT test number	385258722671
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	





MOT #2	2016-09-28 10:01
MOT test number	635967179474
Result	✓ Passed
MOT #1	2015-12-22 12:24
MOT test number	750622286785
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	



Tax & MOT check

✓ Taxed Tax due: 1 April 2025	MOT Expires: 24 April 2025
Tax status	Valid until 1 April
Days left	337
MOT expiry date	24 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lashe
Туре	
Damage 2	AMPLE
Damage 2	E CUT D
Date	 *
Category	 amer
Туре	

Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And the second sec	

	More info >
Plate changes	
See in this check if this BMW had different number plate	5.
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-01-03
Last registration	2024-04-25
Complete history	<u>See info</u>



Registration #1	2013-01-03	11 mi
Registration #2	2015-12-22	67.337 mi
Registration #3	2016-09-28	74.011 mi
Registration #4	2017-09-27	91.046 mi
Registration #5	2018-09-27	104.671 mi
Registration #6	2018-09-28	104.675 mi
Registration #7	2019-09-23	116.182 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		100 JULY 444
Registration #13		11.227 mi





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1983 mm
Height	1690 mm
Length	4877 mm
Wheel base	2933 mm
Kerb weight	2110 kg
Max. allowed weight	2710 kg
Additional information	
Fuel tank capacity	85 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	31768350