





General information

Make	VOLVO
Model	V60 D5 SE LUX NAV AWD
Colour	Blue
Year of manufacture	2016
Top speed	130 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	220 BHP
Max. torque	440 Nm at 3.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F







P66 ACX

Internet history

Entry 1	
Date	2021-02-06
Pictures	10
Listing price	View report

We deliver.

Keep safe & stay at home during COVID-19

6



source: autoonline.co.uk



MOT history

MOT expiry date	2025-03-01
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	7
Total items failed	6

MOT #9	2024-02-09 09:33
MOT test number	477998164382
Result	✓ Passed
Next expiry date	2025-03-01

MOT #8	2023-02-16 16:27
MOT test number	235549309040
Result	✓ Passed

MOT #7	2023-02-14 09:47
MOT test number	873259750048
Result	🗙 Failed
FailNearside Rear Registration plate lamp inoperative in the case of a single lar(ii))	mp or all lamps (4.7.1 (b)
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Items removed from driver's view prior to test	

MOT #6	2022-02-28 08:09
MOT test number	757562519764
Result	✓ Passed





MOT #5	2022-02-23 12:35
MOT test number	754002542197
Result	🗙 Failed
Fail Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
MOT #4	2021-03-02 09:55
MOT test number	917913856854
Result	🗸 Passed
MOT #3	2020-06-29 07:18
MOT test number	546999014236
Result	✓ Passed
MOT #2	2019-12-04 10:23
MOT test number	627216162119
Result	✓ Passed
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice Nearside Front Nail in tyre	
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened ((1.1.14 (a) (ii))
	2010 12 02 11 22

MOT #1	2019-12-03 11:33
MOT test number	388880495722
Result	🗙 Failed
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakene	ed (1.1.14 (a) (ii))
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weaker	ned (1.1.14 (a) (ii))
Fail Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Nearside Front Nail in tyre	



Tax & MOT check

✓ Taxed Tax due: 1 September 2024	✓ MOT Expires: 1 March 2025
Tax status	Valid until 1 September
Days left	124
MOT expiry date	1 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Date	1. the second se
Category	ante
Туре	

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-12-09
Last registration	2024-02-09
Complete history	See info



Registration #1	2016-12-09	19 mi
Registration #2	2019-12-03	34.719 mi
Registration #3	2019-12-04	34.719 mi
Registration #4	2020-06-29	39.798 mi
Registration #5		11.777 au
Registration #6	2021-03-02	39.896 mi
Registration #7		11.777 au
Registration #8		10.202 est
Registration #9		10.202 au
Registration #10		10.202 est
Registration #11		10.207 est





Car features

S0225	Air conditioning
S0295	
S0482	
\$0501	
50566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1865 kg
Max. allowed weight	2505 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11