



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D DRIVE SE
Colour	Silver
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-12-30
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-17
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	16
Total items failed	3

MOT #15	2023-05-09 11:20
MOT test number	340141642692
Result	✓ Passed
Next expiry date	2024-05-17

MOT #14	2022-05-18 09:57
MOT test number	871203558227
Result	✓ Passed

MOT #13	2022-05-17 11:23
MOT test number	554778535254
Result	✗ Failed
MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #12	2021-07-20 15:37
MOT test number	256464178937
Result	✓ Passed

**MOT #11** 2021-07-20 07:45**MOT test number** 874851365289**Result** ✗ Failed**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Emissions not tested (8.2.2.2 (e))**MOT #10** 2020-07-28 09:17**MOT test number** 208407797127**Result** ✓ Passed**Advice** Engine covers and under tray fitted**MOT #9** 2019-08-27 14:59**MOT test number** 866312532912**Result** ✓ Passed**Advice** Covers fitted to engine and under car obscuring view of some testable items**MOT #8** 2018-08-30 13:58**MOT test number** 287526967910**Result** ✓ Passed**Advice** Front wipers smearing on screen but not effecting drivers view of the road**Advice** Covers fitted to engine and under car obscuring view of some testable items**MOT #7** 2017-08-30 15:27**MOT test number** 299319342730**Result** ✓ Passed**Advice** Covers fitted to engine and under car obscuring view of some testable items**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2016-08-30 14:25**MOT test number** 791809223766**Result** ✓ Passed**Advice** Covers fitted to engine and under car**MOT #5** 2016-08-30 14:25**MOT test number** 785443512047**Result** ✗ Failed**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Covers fitted to engine and under car**MOT #4** 2015-09-16 11:20**MOT test number** 567916924559**Result** ✓ Passed**Advice** Covers fitted to engine and under car**MOT #3** 2014-09-15 09:24**MOT test number** 387088754251**Result** ✓ Passed**MOT #2** 2014-09-15 09:24**MOT test number** 769248154226**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #1	2013-09-16 09:38
MOT test number	437219553252
Result	✓ Passed
Notice	Front tyres wearing low on inner edge
Notice	Sill covers fitted
Notice	Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
17 May 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	17 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	RF60FNR
Plate since	2019-09-28
Current registration	RF60FNR
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-24
Last registration	2023-05-09
Complete history	See info



Registration #1	2010-09-24	20 mi
Registration #2	2013-09-16	23.706 mi
Registration #3	2014-09-15	32.501 mi
Registration #4	2015-09-16	39.227 mi
Registration #5	2016-08-30	45.011 mi
Registration #6	2016-08-30	45.011 mi
Registration #7	2017-08-30	49.755 mi
Registration #8	2018-08-30	54.872 mi
Registration #9	2019-05-09	55,000 (max)
Registration #10	2020-05-09	55,000 (max)
Registration #11	2021-05-09	55,000 (max)
Registration #12	2022-05-09	55,000 (max)
Registration #13	2023-05-09	55,000 (max)
Registration #14	2024-05-09	55,000 (max)
Registration #15	2025-05-09	55,000 (max)
Registration #16	2026-05-09	55,000 (max)

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1382 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	957548