



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Blue
Year of manufacture	2007
Top speed	111 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	180 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-11-09
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-30
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	11
Total items failed	13

MOT #20	2023-08-31 11:00
MOT test number	606575123847
Result	✓ Passed
Next expiry date	2024-08-30

MOT #19	2022-11-02 11:44
MOT test number	433962184060
Result	✓ Passed

MOT #18	2021-11-18 14:01
MOT test number	401440709166
Result	✓ Passed

Minor Offside Front Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #17	2021-11-10 10:58
MOT test number	273005730403
Result	✗ Failed

Minor Offside Front Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Fail Nearside Front Front passenger door cannot be opened from inside the vehicle (6.2.3 (a))

Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #16** 2020-10-23 10:59**MOT test number** 244043624849**Result** ✓ Passed**MOT #15** 2019-03-28 13:44**MOT test number** 336763769323**Result** ✓ Passed**MOT #14** 2019-03-27 17:06**MOT test number** 762746319964**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #13** 2018-04-12 08:34**MOT test number** 541769114329**Result** ✓ Passed**MOT #12** 2018-04-06 13:05**MOT test number** 383998923303**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Rear registration plate insecure (6.3.1b)**Fail** Front registration plate insecure (6.3.1b)

**MOT #11** 2017-04-27 16:03**MOT test number** 350996903280**Result** ✓ Passed**MOT #10** 2017-04-27 10:31**MOT test number** 128031288292**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Nearside Front Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #9** 2016-04-21 12:00**MOT test number** 957661357391**Result** ✓ Passed**MOT #8** 2016-04-21 08:23**MOT test number** 204262612058**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Advice** Nearside Front Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**MOT #7** 2015-03-31 09:37**MOT test number** 499970095068**Result** ✓ Passed**MOT #6** 2014-04-09 10:10**MOT test number** 827179694054**Result** ✓ Passed

**MOT #5** 2013-02-26 12:07**MOT test number** 655167353061**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-02-28 14:46**MOT test number** 879699152040**Result** ✓ Passed**Notice** Damage to n/s outer sill**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #3** 2012-02-28 10:29**MOT test number** 517649752004**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Damage to n/s outer sill**Fail** Nearside Stop lamp not working (1.2.1b)**MOT #2** 2010-09-10 15:34**MOT test number** 380473050413**Result** ✓ Passed**MOT #1** 2010-09-10 14:11**MOT test number** 714283650253**Result** ✗ Failed**Fail** Nearside Outer Front constant velocity joint is excessively worn (2.5.C.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
30 August 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	30 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 AK57KFW
Plate since	2019-06-29
Current registration	 AK57KFW
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-12-24
Last registration	2023-08-31
Complete history	See info



Registration #1	2007-12-24	23 mi
Registration #2	2010-09-10	22.474 mi
Registration #3	2010-09-10	22.475 mi
Registration #4	2012-02-28	33.587 mi
Registration #5	2012-02-28	33.587 mi
Registration #6	2013-02-26	40.310 mi
Registration #7	2014-04-09	45.159 mi
Registration #8	2015-03-31	50.756 mi
Registration #9	2016-04-21	55.579 mi
Registration #10	2016-04-21	55.580 mi
Registration #11	2017-04-27	60.293 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi
Registration #17	2019-05-29	75.277 mi
Registration #18	2019-05-29	75.277 mi
Registration #19	2019-05-29	75.277 mi
Registration #20	2019-05-29	75.277 mi
Registration #21	2019-05-29	75.277 mi
Registration #22	2019-05-29	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1314 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BFS 056261