



report date: 2024-03-28

General information

Make	FORD
Model	GALAXY TITANIUM TDCI
Colour	White
Year of manufacture	2010
Top speed	122 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 3.250 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	159 g/km
CO2 label	G



Internet history

Entry 1

Date	2021-08-15
Pictures	8
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-06
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	50
Total items failed	13



MOT #15		2023-12-01 16:19
MOT test number		438133378684
Result		✓ Passed
Next expiry date		2024-12-06
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Advice	Suspension arm corroded but not seriously weakened all of them, front and rear (5.3.3 (b) (i))	
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement most rear bush (5.3.4 (a) (i))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Advice	Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))	
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))	
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Advice	Rear Child Seat fitted not allowing full inspection of adult belt both seats	
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement most rear bush (5.3.4 (a) (i))	
Minor	Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt cracking and starting to split (2.1.3 (g) (i))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Rear Direction indicator slightly discoloured both sides (4.4.3 (a))	

**MOT #14**

2023-11-27 17:08

MOT test number

783160164185

Result**✗ Failed**

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement most rear bush (5.3.4 (a) (i))
- Advice** Rear Direction indicator slightly discoloured both sides (4.4.3 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt both seats
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Suspension arm corroded but not seriously weakened all of them, front and rear (5.3.3 (b) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement most rear bush (5.3.4 (a) (i))
- Advice** Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Rear Registration plate lamp likely to become detached (4.7.1 (c) (ii))
- Fail** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #13**

2022-12-07 10:17

MOT test number

802416083637

Result

✓ Passed

Minor Nearside Registration plate lamp insecure (4.7.1 (c) (i))**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Minor** Offside Registration plate lamp insecure (4.7.1 (c) (i))**MOT #12**

2022-12-01 11:19

MOT test number

951197312547

Result

✗ Failed

Minor Nearside Registration plate lamp insecure (4.7.1 (c) (i))**Fail** Nearside Rear Suspension arm pin or bush excessively worn trailing arm. (5.3.4 (a) (i))**Fail** Central Exhaust system insecure (6.1.2 (a))**Minor** Offside Registration plate lamp insecure (4.7.1 (c) (i))**Fail** Offside Side repeater not working (4.4.1 (a) (ii))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm. (5.3.4 (a) (i))**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**MOT #11**

2021-12-01 11:44

MOT test number

954291204352

Result

✓ Passed

Advice Offside Front Nail in tyre**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2021-12-01 11:44**MOT test number** 342164758848**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Offside Front Nail in tyre**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #9** 2020-11-04 11:10**MOT test number** 690701208267**Result** ✓ Passed**Advice** Rear and front brake pads and discs worn low-o/s/r/ tyre walls perished-**MOT #8** 2019-05-30 13:34**MOT test number** 658046622667**Result** ✓ Passed**MOT #7** 2018-05-31 12:47**MOT test number** 849881921196**Result** ✓ Passed**MOT #6** 2017-06-03 14:24**MOT test number** 824003068805**Result** ✓ Passed

**MOT #5** 2016-06-03 13:24**MOT test number** 943215820255**Result** ✓ Passed**Advice** REar bumper distorted**Advice** Off side rear lamps cracked / (no white light)**Advice** Front bumper damaded**MOT #4** 2016-06-03 11:44**MOT test number** 585676672400**Result** ✗ Failed**Advice** Front bumper damaded**Advice** REar bumper distorted**Fail** Brake pedal anti-slip provision missing (3.3.A.1b)**Advice** Off side rear lamps cracked / (no white light)**Fail** Upper Stop lamp not working (1.2.1b)**MOT #3** 2015-05-28 10:10**MOT test number** 187688845115**Result** ✓ Passed**MOT #2** 2015-05-28 10:10**MOT test number** 209448945467**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)



MOT #1	2013-12-02 15:48
MOT test number	989036833397
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
6 December 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	6 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-29
Last registration	2023-12-01
Complete history	See info



Registration #1	2010-09-29	16 mi
Registration #2	2013-12-02	34.482 mi
Registration #3	2015-05-28	58.985 mi
Registration #4	2016-06-03	77.984 mi
Registration #5	2016-06-03	77.984 mi
Registration #6	2017-06-03	84.251 mi
Registration #7	2018-05-31	89.132 mi
Registration #8	2019-05-30	93.621 mi
Registration #9	2020-05-29	95.377 mi
Registration #10	2021-05-29	95.377 mi
Registration #11	2022-05-29	95.377 mi
Registration #12	2023-05-29	95.377 mi
Registration #13	2024-05-29	95.377 mi
Registration #14	2025-05-29	95.377 mi
Registration #15	2026-05-29	95.377 mi
Registration #16	2027-05-29	95.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number

AU21080