



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	MERIVA EXCLUSIV AC
Colour	Blue
Year of manufacture	2015
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	118 BHP
Max. torque	200 Nm at 1.850 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	166 g/km
CO2 label	H






Internet history

Entry 2


Date	2021-09-04
Pictures	28
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-29
Pictures	28
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-09-13
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	11
Total items failed	2

MOT #9	2023-09-13 11:25
MOT test number	506335906546
Result	✓ Passed
Next expiry date	2024-09-13
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #8	2022-09-06 10:19
MOT test number	296937212520
Result	✓ Passed

MOT #7	2021-09-14 12:56
MOT test number	828978551858
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #6** 2020-12-29 16:48**MOT test number** 882768913602**Result** ✓ Passed

**Advice** Oil leak, but not excessive Risk of fire due to oil dripping on to front pipe/catalytic converter (8.4.1 (a) (i))

**Advice** Tyre slightly damaged/cracking or perishing Both rear tyres perished to sidewall (5.2.3 (d) (ii))

**MOT #5** 2020-12-29 14:32**MOT test number** 996824677514**Result** ✗ Failed

**Fail** Tyre(s) of different sizes are fitted on the same axle. space saver/temp use fitted to offside front (5.2.3 (b))

**Advice** Tyre slightly damaged/cracking or perishing Both rear tyres perished to sidewall (5.2.3 (d) (ii))

**Advice** Oil leak, but not excessive Risk of fire due to oil dripping on to front pipe/catalytic converter (8.4.1 (a) (i))

**MOT #4** 2020-01-13 11:10**MOT test number** 398174152242**Result** ✓ Passed

**Advice** Tyre slightly damaged/cracking or perishing ALL TYRES CRACKING (5.2.3 (d) (ii))

**MOT #3** 2020-01-13 10:53**MOT test number** 581591892785**Result** ✗ Failed

**Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Tyre slightly damaged/cracking or perishing ALL TYRES CRACKING (5.2.3 (d) (ii))

**Advice** Vehicles internal headlight adjuster altered to recheck lights

**MOT #2** 2019-02-14 11:19**MOT test number** 843206317051**Result** ✓ Passed



MOT #1	2018-02-09 14:01
MOT test number	302156535790
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
13 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	13 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>HK64OSA</b>
Plate since	2019-09-29
Current registration	 <b>HK64OSA</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-02-20
Last registration	2023-09-13
Complete history	<a href="#">See info</a>



Registration #1	2015-02-20	7 mi
Registration #2	2018-02-09	9.478 mi
Registration #3	2019-02-14	13.859 mi
Registration #4	2020-01-13	19.064 mi
Registration #5	2020-01-13	19.064 mi
Registration #6	2020-12-29	23.257 mi
Registration #7	2020-01-13	19.064 mi
Registration #8	2020-01-13	19.064 mi
Registration #9	2020-01-13	19.064 mi
Registration #10	2020-01-13	19.064 mi
Registration #11	2020-01-13	19.064 mi
Registration #12	2020-01-13	19.064 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1486 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14NEL -19KB8375LUH