



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	VITO 120 CDI LONG P/V
Colour	Silver
Year of manufacture	2009
Gearbox	5 speed automatic

Engine & fuel consumption

Power	204 BHP
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2021-01-13
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	16
Total items failed	3

MOT #12 2020-01-14 11:36

MOT test number 451451581167

Result ✓ Passed

Next expiry date 2021-01-13

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Exhaust mounting defective (6.1.2 (a))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #11 2018-12-21 15:47

MOT test number 139036220774

Result ✓ Passed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Centre exhaust clamp missing but is not blowing

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2018-01-12 15:58**MOT test number** 269730805460**Result** ✓ Passed**MOT #9** 2018-01-12 15:43**MOT test number** 360643399609**Result** ✗ Failed**Fail** Offside Rear Rear fog lamp not working (1.3.2b)**MOT #8** 2016-10-19 11:40**MOT test number** 314854857830**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Exhaust has a minor leak of exhaust gases front flexi (7.1.2)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Centre and rear exhaust joins no clamps**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #7** 2016-05-05 08:31**MOT test number** 206974563671**Result** ✓ Passed**MOT #6** 2015-04-29 09:14**MOT test number** 247369315408**Result** ✓ Passed**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1a)



MOT #5	2014-05-01 15:29
MOT test number	686541324124
Result	✓ Passed
MOT #4	2014-05-01 15:29
MOT test number	736911824191
Result	✗ Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)
MOT #3	2013-05-03 10:53
MOT test number	207813823419
Result	✓ Passed
MOT #2	2012-05-02 11:29
MOT test number	908693122134
Result	✓ Passed
MOT #1	2012-05-02 11:29
MOT test number	448823722178
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too low (1.8)



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 GL09ZKC
Plate since	2019-06-29
Current registration	 GL09ZKC
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2009-03-16
Last registration	2020-01-14
Complete history	See info



Registration #1	2009-03-16	27 mi
Registration #2	2012-05-02	50.423 mi
Registration #3	2013-05-03	71.297 mi
Registration #4	2014-05-01	79.666 mi
Registration #5	2015-04-29	99.048 mi
Registration #6	2016-05-05	132.132 mi
Registration #7	2017-05-02	151.277 mi
Registration #8	2018-05-02	161.277 mi
Registration #9	2019-05-02	171.277 mi
Registration #10	2020-01-14	181.277 mi
Registration #11	2020-01-14	191.277 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Engine number	64299040863444