



report date: 2024-03-28

General information

Make	HONDA
Model	FR-V CTDI SPORT
Colour	Black
Year of manufacture	-
Top speed	103 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	340 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-14
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #14	2021-03-24 12:39
MOT test number	283215187018
Result	✓ Passed
Next expiry date	2022-03-29
Advice	All rear suspension components corroded
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	All underside of vehicle is corrode

MOT #13	2020-03-24 17:40
MOT test number	982913690344
Result	✓ Passed
Advice	Offside Front Macpherson strut mounting corroded but not seriously weakened bearing tight (5.3.3 (b) (i))
Advice	All rear suspension corroded not excessive
Advice	Nearside Front Macpherson strut mounting corroded but not seriously weakened bearing tight (5.3.3 (b) (i))
Advice	All front suspension corroded not excessive

MOT #12	2019-03-30 15:34
MOT test number	485051925001
Result	✓ Passed
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #11** 2017-11-04 12:12**MOT test number** 196134921813**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear Tie bar/rod has slight play in a pin/bush (2.4.G.2)**Advice** Rear Anti-roll bar synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #10** 2016-11-26 14:08**MOT test number** 526346158518**Result** ✓ Passed**MOT #9** 2015-11-17 12:26**MOT test number** 748631416086**Result** ✓ Passed**MOT #8** 2014-11-29 10:31**MOT test number** 507723034320**Result** ✓ Passed**MOT #7** 2013-11-02 09:30**MOT test number** 946236203395**Result** ✓ Passed**MOT #6** 2013-11-02 09:30**MOT test number** 938596403339**Result** ✗ Failed**Pass with rectification** Nearside Front Anti-roll bar linkage damaged and seriously weakened (2.4.G.1)

**MOT #5** 2012-11-21 12:13**MOT test number** 907986222348**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in offside rear tyre**MOT #4** 2011-11-21 16:47**MOT test number** 816775521316**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #3** 2011-11-21 09:40**MOT test number** 627605221388**Result** ✗ Failed**Fail** Front registration plate character(s) incorrectly spaced (6.3.4a)**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Fail** Nearside Windscreen wiper blade insecure (8.2.2)**Fail** Rear registration plate character(s) incorrectly spaced (6.3.4a)**MOT #2** 2010-11-22 16:37**MOT test number** 914066520351**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2009-11-18 13:02
MOT test number	871582629307
Result	✓ Passed



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	YE56CVA
Plate since	2019-09-29
Current registration	YE56CVA
Plate since	2019-09-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2006-11-30
Last registration	2021-03-24
Complete history	See info



Registration #1	2006-11-30	26 mi
Registration #2	2009-11-18	25.170 mi
Registration #3	2010-11-22	36.549 mi
Registration #4	2011-11-21	47.201 mi
Registration #5	2011-11-21	47.203 mi
Registration #6	2012-11-21	57.328 mi
Registration #7	2013-11-02	67.194 mi
Registration #8	2014-11-29	77.847 mi
Registration #9	2015-03-29	88.500 mi
Registration #10	2015-03-29	88.500 mi
Registration #11	2015-03-29	88.500 mi
Registration #12	2015-03-29	88.500 mi
Registration #13	2015-03-29	88.500 mi
Registration #14	2015-03-29	88.500 mi
Registration #15	2015-03-29	88.500 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2113 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1584 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Engine number	N22A11503858