



report date: 2024-03-28

General information

Make	NISSAN
Model	ALMERA S
Colour	Blue
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	12.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	114 BHP
Max. torque	163 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-01-02
Pictures	7
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history****MOT #23** 2020-12-01 15:17**MOT test number** 565848294689**Result** ✓ Passed**Next expiry date** 2021-11-30**Advice** Nearside Non obligatory mirror damaged**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #22** 2020-11-28 11:48**MOT test number** 230828378010**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases centre pipe broken (6.1.2 (a))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))**Advice** Nearside Non obligatory mirror damaged**Fail** Emissions not tested exhaust broken in two (8.2.1.2 (d))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #21** 2019-05-30 14:47**MOT test number** 986162408848**Result** ✓ Passed**Advice** Spare tyre defective**MOT #20** 2018-04-26 15:01**MOT test number** 637278262960**Result** ✓ Passed**Advice** Spare tyre defective

**MOT #19** 2017-04-13 15:51**MOT test number** 410907057748**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #18** 2017-04-13 12:37**MOT test number** 763642843797**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Headlamp excessively damaged so that the light output is severely reduced bulb holder broken away from reflector (1.7.5a)**MOT #17** 2016-04-08 11:55**MOT test number** 194399713185**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #16** 2016-04-07 13:13**MOT test number** 786568907266**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Fail** Offside Headlamp aim beam image obviously incorrect dim no light out put (1.8.A.1b)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Fail** Nearside Headlamp insecure (1.7.3)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)**Fail** Nearside Headlamp aim too low (1.8)**Fail** Supplementary Restraint System warning lamp indicates a fault air bag light (5.4.2)**MOT #15** 2015-04-11 13:57**MOT test number** 209121505447**Result** ✓ Passed

**MOT #14**

2015-04-10 11:35

**MOT test number**

857120105197

**Result****✗ Failed**

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Offside Rear Stop lamp not working (1.2.1b)
- Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Fail** Offside Front Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)

**MOT #13**

2014-01-14 15:54

**MOT test number**

449564714015

**Result****✓ Passed****MOT #12**

2014-01-14 10:07

**MOT test number**

508284514065

**Result****✗ Failed**

- Fail** Service brake: efficiency below requirements (3.7.B.7)

**MOT #11**

2013-08-23 11:07

**MOT test number**

317205733234

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #10** 2012-08-14 09:51**MOT test number** 747027022203**Result** ✓ Passed**MOT #9** 2012-07-13 14:51**MOT test number** 677665492125**Result** ✓ Passed**MOT #8** 2012-07-13 14:51**MOT test number** 276345092150**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (1.8)**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**MOT #7** 2011-04-18 16:43**MOT test number** 125928101113**Result** ✓ Passed**Notice** Offside front tyre worn on inner edges (raised tread)**MOT #6** 2011-04-18 13:24**MOT test number** 337978701148**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside rear brake binding (3.7.B.1)**Notice** Offside front tyre worn on inner edges (raised tread)**Fail** Nearside rear brake binding (3.7.B.1)

**MOT #5** 2010-05-04 10:38**MOT test number** 163824520144**Result** ✓ Passed**MOT #4** 2009-04-16 17:32**MOT test number** 873106209103**Result** ✓ Passed**Notice** Nail in nearside front tyre**MOT #3** 2008-05-08 16:14**MOT test number** 662339928176**Result** ✓ Passed**Notice** O/s/f & n/s/f tyres wearing slightly on outer & inner edges**MOT #2** 2008-05-06 14:15**MOT test number** 233867028409**Result** ✗ Failed**Pass with rectification** Parking brake lever has no reserve travel (3.1.6b)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** O/s/f & n/s/f tyres wearing slightly on outer & inner edges**MOT #1** 2007-05-11 15:09**MOT test number** 860231837165**Result** ✓ Passed





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-03-26
Last registration	2020-12-01
Complete history	<a href="#">See info</a>



Registration #1	2004-03-26	7 mi
Registration #2	2007-05-11	12.736 mi
Registration #3	2008-05-06	15.217 mi
Registration #4	2008-05-08	15.234 mi
Registration #5	2009-04-16	16.060 mi
Registration #6	2010-05-04	19.012 mi
Registration #7	2011-04-18	20.946 mi
Registration #8	2011-04-18	20.946 mi
Registration #9	2012-07-13	23.163 mi
Registration #10	2012-08-14	23.168 mi
Registration #11	2013-08-23	26.730 mi
Registration #12	2014-01-14	27.903 mi
Registration #13	2015-01-20	28.277 mi
Registration #14	2015-01-20	28.277 mi
Registration #15	2015-01-20	28.277 mi
Registration #16	2015-01-20	28.277 mi
Registration #17	2015-01-20	28.277 mi
Registration #18	2015-01-20	28.277 mi
Registration #19	2015-01-20	28.277 mi
Registration #20	2015-01-20	28.277 mi
Registration #21	2015-01-20	28.277 mi
Registration #22	2015-01-20	28.277 mi
Registration #23	2015-01-20	28.277 mi
Registration #24	2015-01-20	28.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1199 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	326556