



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI S 5STR
Colour	Grey
Year of manufacture	-
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-23
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #21	2022-04-01 16:43
MOT test number	669624747786
Result	✓ Passed
Next expiry date	2023-03-31
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #20	2022-03-26 14:07
MOT test number	998560487651
Result	✗ Failed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Fail	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #19	2021-03-01 12:52
MOT test number	976574522117
Result	✓ Passed
Advice	O/s rear shock absorber upper casing loose
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18**

2021-02-19 11:01

MOT test number

161721298306

Result**✗ Failed**

- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** O/s rear shock absorber upper casing loose
- Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17

2020-02-21 15:49

MOT test number

498631074923

Result**✓ Passed**

- Advice** Offside Outer c.v. boot leaking slightly
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Slight imbalance of front brakes

MOT #16

2020-02-21 09:12

MOT test number

697509087995

Result**✗ Failed**

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Outer c.v. boot leaking slightly
- Advice** Slight imbalance of front brakes
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn wishbone rear mounting (5.3.4 (a) (i))
- Advice** Signs of engine mounting wear
- Advice** Washers could be better

**MOT #15** 2019-03-12 10:57**MOT test number** 717713764614**Result** ✓ Passed**MOT #14** 2018-05-11 15:57**MOT test number** 343947616278**Result** ✓ Passed**Advice** Offside Rear tyre cracking**MOT #13** 2018-05-11 09:22**MOT test number** 646463280438**Result** ✗ Failed**Advice** Offside Rear tyre cracking**Fail** Emissions not tested (7.3.A.1)**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Fail** Nearside Front Front suspension has excessive play in a pin or bush of a lower wishbone inner bearing yellow chalk inner front bush (2.5.B.1a)**MOT #12** 2017-05-09 14:37**MOT test number** 189501950561**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Both rear tyres cracking between tread cords not exposed**MOT #11** 2016-04-29 08:50**MOT test number** 256558238493**Result** ✓ Passed**Advice** Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Nearside Front tyre shows some damage to sidewall

**MOT #10** 2015-04-28 10:49**MOT test number** 459958115184**Result** ✓ Passed**MOT #9** 2014-05-06 17:06**MOT test number** 216756924187**Result** ✓ Passed**Advice** Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Lower engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)**Advice** Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #8** 2013-05-07 14:26**MOT test number** 936847123180**Result** ✓ Passed**MOT #7** 2012-05-10 16:32**MOT test number** 667841932107**Result** ✓ Passed**MOT #6** 2012-05-09 09:16**MOT test number** 706840232176**Result** ✗ Failed**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)



MOT #5	2011-05-14 11:41
---------------	------------------

MOT test number	149274031120
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2011-05-14 09:19
---------------	------------------

MOT test number	259814631414
------------------------	--------------

Result	✗ Failed
---------------	----------

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

MOT #3	2010-05-11 17:25
---------------	------------------

MOT test number	761621830141
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2009-05-11 12:29
---------------	------------------

MOT test number	243971539104
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2008-05-17 13:14
---------------	------------------

MOT test number	272378638475
------------------------	--------------

Result	✓ Passed
---------------	----------



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-09-30
Last registration	2022-04-01
Complete history	See info



Registration #1	2005-09-30	17 mi
Registration #2	2008-05-17	28.497 mi
Registration #3	2009-05-11	35.508 mi
Registration #4	2010-05-11	41.852 mi
Registration #5	2011-05-14	48.839 mi
Registration #6	2011-05-14	48.839 mi
Registration #7	2012-05-09	54.670 mi
Registration #8	2012-05-10	54.670 mi
Registration #9	2013-05-07	59.821 mi
Registration #10	2014-05-06	64.427 mi
Registration #11	2015-04-28	69.538 mi
Registration #12	2016-04-29	74.136 mi
Registration #13	2016-05-20	75.277 mi
Registration #14	2016-05-20	75.277 mi
Registration #15	2016-05-20	75.277 mi
Registration #16	2016-05-20	75.277 mi
Registration #17	2016-05-20	75.277 mi
Registration #18	2016-05-20	75.277 mi
Registration #19	2016-05-20	75.277 mi
Registration #20	2016-05-20	75.277 mi
Registration #21	2016-05-20	75.277 mi
Registration #22	2016-05-20	75.277 mi
Registration #23	2016-05-20	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BKC 732958