




report date: 2024-03-28

General information

Make	VOLVO
Model	XC90 D5 SE LUX AWD
Colour	Blue
Year of manufacture	2011
Top speed	127 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	200 BHP
Max. torque	420 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.7 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.0 mpg
CO2 emission	219 g/km
CO2 label	K





Internet history

Entry 2

Date	2024-03-22
Pictures	45
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-03-22
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	37
Total items failed	8

MOT #16	2024-03-23 17:09
MOT test number	525071014258
Result	✓ Passed
Next expiry date	2025-03-22

MOT #15	2023-07-27 11:27
MOT test number	320314916289
Result	✓ Passed
Advice	Coil spring corroded both rear (5.3.1 (b) (i))

MOT #14	2022-07-04 15:04
MOT test number	270186633916
Result	✓ Passed

MOT #13	2021-07-06 12:57
MOT test number	758154298328
Result	✓ Passed

**MOT #12**

2021-07-06 08:32

MOT test number

902318934793

Result

✗ Failed

- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Nearside Front Headlamp light intensity severely reduced (4.1.4 (a))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #11

2020-07-06 14:34

MOT test number

794368163591

Result

✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Light cluster cracked
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Under-trays fitted obscuring some underside components
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Outer sidewall (5.2.3 (d) (i))
- Advice** Engine covers fitted obscuring some components in the engine bay

**MOT #10**

2020-07-06 14:34

MOT test number

914931839564

Result**✗ Failed****Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Light cluster cracked**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Outer sidewall (5.2.3 (d) (i))**Advice** Under-trays fitted obscuring some underside components**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Rear Direction Indicator slightly discoloured (4.4.3 (a))**MOT #9**

2019-07-03 14:20

MOT test number

840735423565

Result**✓ Passed****Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Engine covers fitted obscuring some components in the engine bay**Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**Advice** Under-trays fitted obscuring some underside components**MOT #8**

2018-07-06 08:00

MOT test number

349775817450

Result**✓ Passed****Advice** Engine covers fitted obscuring some components in the engine bay**Advice** Under-trays fitted obscuring some underside components**Advice** Parking brake efficiency only just met

**MOT #7** 2018-07-04 13:25**MOT test number** 176742326606**Result** ✗ Failed**Advice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Under-trays fitted obscuring some underside components**Advice** Parking brake efficiency only just met**MOT #6** 2017-06-21 13:25**MOT test number** 295371626748**Result** ✓ Passed**Advice** Engine covers fitted obscuring some components in the engine bay**Advice** Parking brake efficiency only just met**Advice** Under-trays fitted obscuring some underside components**Advice** Nearside Rear low tyre pressure**Advice** Offside Front Tyre worn close to the legal limit 3.0mm (4.1.E.1)**MOT #5** 2016-06-23 13:31**MOT test number** 827976893135**Result** ✓ Passed**Advice** Engine covers fitted obscuring some components in the engine bay**Advice** Under-trays fitted obscuring some underside components

**MOT #4** 2016-06-23 13:31**MOT test number** 160096914633**Result** ✗ Failed**Advice** Under-trays fitted obscuring some underside components**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2015-06-26 14:47**MOT test number** 149067575127**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #2** 2015-06-25 15:08**MOT test number** 316606275192**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2014-07-01 14:54**MOT test number** 936822084181**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
5 April 2024

✓

MOT

Expires:
22 March 2025

Tax status	Expired at 5 April 2024
Days left	23 days too late
MOT expiry date	22 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-07-08
Last registration	2024-03-23
Complete history	See info



Registration #1	2011-07-08	18 mi
Registration #2	2014-07-01	28.725 mi
Registration #3	2015-06-25	39.651 mi
Registration #4	2015-06-26	39.651 mi
Registration #5	2016-06-23	51.301 mi
Registration #6	2016-06-23	51.301 mi
Registration #7	2017-06-21	63.003 mi
Registration #8	2018-07-04	74.166 mi
Registration #9	2018-07-06	74.252 mi
Registration #10	2019-07-03	84.517 mi
Registration #11	2019-06-20	95.777 mi
Registration #12	2019-06-20	95.777 mi
Registration #13	2019-06-20	95.777 mi
Registration #14	2019-06-20	95.777 mi
Registration #15	2019-06-20	95.777 mi
Registration #16	2019-06-20	95.777 mi
Registration #17	2019-06-20	95.777 mi
Registration #18	2019-06-20	95.777 mi
Registration #19	2019-06-20	95.777 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4807 mm
Wheel base	2857 mm
Kerb weight	2158 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1044305