





# General information

### Engine & fuel consumption

Power	74 BHP
Max. torque	119 Nm at 3.500 rpm
Engine capacity	1.349 cc
Cylinders	4
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	С







# Internet history

Entry 2	
Date	2021-06-12
Pictures	24
Listing price	View report



source: autotrader.co.uk

Entry 1	
Date	2021-06-10
Pictures	23
Listing price	View report



source: yesauto.com









# MOT history

MOT expiry date	2024-05-28
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #10	2023-05-15 12:19
MOT test number	365905812609
Result	✓ Passed
Next expiry date	2024-05-28
Minor Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)	))
Advice Nearside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))	

МОТ #9	2022-05-18 08:21
MOT test number	311946307150
Result	✓ Passed

MOT #8	2021-05-29 08:42
MOT test number	981791749041
Result	✓ Passed

MOT #7		2021-02-09 10:22
MOT test	number	886218267004
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #6	2020-02-10 15:34
MOT test number	447168490957
Result	✓ Passed
Advice Minor runout in both rear tyres	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #5	2020-02-10 11:54
MOT test number	829925671126
Result	🗙 Failed
<b>Fail</b> Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Minor runout in both rear tyres	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #4	2019-02-08 09:36
MOT test number	133163460670
Result	✓ Passed
Advice Minor run out in both rear tyres	

МОТ #3	2018-02-12 11:18
MOT test number	140056188883
Result	✓ Passed

MOT #2	2017-02-13 10:25
MOT test number	120235879124
Result	✓ Passed





MOT #1		2016-02-04 10:41
MOT test I	number	455410513758
Result		✓ Passed
Advice	Offside Front Outer Tyre sidewall has a cut in it but not deep enough	to expose ply or chord.



Tax & MOT check

<b>Tax due:</b> 1 July 2024	✓ Taxed	<b>Expires:</b> 28 May 2024	✓ мот
Tax status			Valid until 1 July
Days left			62
MOT expiry date			28 May 2024
Full MOT history			See MOT history
Tax calculation			
Vahiele elece		40	

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E E H - S - A
Date	*
Category	AMP.
Туре	

#### Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





## Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

*******	
***********	
*******	
******	
***********	
*******	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Correct registration	
Plate since	
	More info >





### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-02-20
Last registration	2023-05-15
Complete history	See info



Registration #1	2013-02-20	18 mi
Registration #2	2016-02-04	16.573 mi
Registration #3	2017-02-13	22.426 mi
Registration #4	2018-02-12	28.779 mi
Registration #5	2019-02-08	34.231 mi
Registration #6	2020-02-10	39.085 mi
Registration #7	2020-02-10	39.085 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.117 mi



HN62GUF report date: 2024-03-29

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1695 mm
Height	1475 mm
Length	3885 mm
Wheel base	2490 mm
Kerb weight	1030 kg
Max. allowed weight	1485 kg
Additional information	
Additional information Fuel tank capacity	42
	42 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5