





report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO EASY
Colour	Black
Year of manufacture	2014
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	126 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2022-02-11

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

Advice

MOT expiry date	2025-03-19
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	12
Total items failed	7

MOT #8	2024-03-06 14:57
MOT test number	672184440208
Result	✓ Passed
Next expiry date	2025-03-19
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

Pass with rectification Offside Front Direction indicator incorrect colour (4.4.3 (a))	MOT #7		2024-03-06 14:57
Pass with rectification Offside Front Direction indicator incorrect colour (4.4.3 (a))	MOT test number		550365920777
	Result		X Failed
Advice hearside from tyre slightly damaged/cracking of perishing (5.2.5 (d) (ll))		Offside Front Direction indicator incorrect colour (4.4.3 (a)) Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #6	2023-03-20 15:05
MOT test number	749912873387
Result	✓ Passed
MOT #5	2022-02-11 16:17
MOT test number	842090844870
Result	✓ Passed

Brake disc worn, pitted or scored, but not seriously weakened Both sides front (1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #4 2021-03-11 11:02

MOT test number 155534069417

Result ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3 2019-09-18 14:11

MOT test number 514996814513

Result \square Passed

Advice Front Anti roll bar (full assembly) not in place... may not be original spec equipment on this vehicle... benefit of doubt given

Advice Front Tyre worn close to legal limit/worn on edge both sides bald on inner edges / close to chords (5.2.3 (e))

MOT #2 2019-09-13 12:59

MOT test number 247387586732

Result X Failed

Fail Windscreen washer not working (3.5 (a))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside day-time running light inop

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Driver's view of the road through the swept area of the windscreen materially affected by an obstruction sun visor does not secure out of view (3.1 (a) (ii))

Advice Front Tyre worn close to legal limit/worn on edge both sides bald on inner edges / close to chords (5,2,3 (e))

Advice Front Anti roll bar (full assembly) not in place... may not be original spec equipment on this vehicle... benefit of doubt given

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2017-11-02 13:53

MOT test number 725520977077

CarCheck.co.uk page 5/12



YE64OGT report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	19 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
	-
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



YE64OGT report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NK SIK
Plate since	
Current registration	UK ONE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-10-31
Last registration	2024-03-06
Complete history	See info



Registration #1	2014-10-31	15 mi
Registration #2	2017-11-02	45.103 mi
Registration #3	2019-09-13	65.213 mi
Registration #4	2019-09-18	65.214 mi
Registration #5	2021-03-11	66.040 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.777 ea
-		11.77 m
Registration #7		11,777 es 11,777 es 11,777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number 0798077