





report date: 2024-03-28

General information

Make	JAGUAR
Model	S-TYPE V6 SE
Colour	Silver
Year of manufacture	2007
Top speed	145 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	299 Nm at 4.100 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.5 mpg
Consumption extra urban	35.3 mpg
Consumption combined	26.4 mpg
CO2 emission	259 g/km
CO2 label	M



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

_	_	_		_	-
드	n	C	ľν	7	1

Life y 1	
Date	2021-07-15
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



DG57EEX report date: 2024-03-28

MOT history

MOT expiry date	2024-10-23
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	18
Total items failed	5

MOT #18		2023-10-23 12:39
MOT test	number	256714184929
Result		✓ Passed
Next expi	ry date	2024-10-23
Advice	Offside Front Tyre slightly damaged (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #17		2022-10-24 17:30
MOT test number		861767096611
Result		✓ Passed
MOT #16		2022-10-24 17:30
MOT test number		559230742711
Result		X Failed
Pass with rectification	Nearside Headlamp not working on main beam (4.1.1 (a) (ii))	

MOT #15	2021-08-02 13:51
MOT test	number 754430090129
Result	✓ Passed
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number

Result

Advice Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #13

MOT test number

Result

Advice Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Minor Offside Front Windscreen wiper blade defective Rubber split on end (3.4 (b) (i))

Minor Nearside Front Windscreen wiper blade defective Rubber split on end (3.4 (b) (i))

MOT #12

MOT test number

Result

Minor

Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor

Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #11

MOT test number

928692236425

Result

Advice
(2.4.G.2)

Rear Lower Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt both

 MOT #10
 2017-01-19 16:30

 MOT test number
 259910272694

 Result
 ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #9 2017-01-19 12:03

MOT test number 730231598297

Result X Failed

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #8 2016-01-22 15:03

MOT test number 936886367826

Result ✓ Passed

MOT #7 2016-01-21 13:35

MOT test number 139410266354

Result X Failed

Fail Nearside Rear Inner Tie bar/rod ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Nearside Rear Shock absorber has a serious fluid leak (2.7.3)

Fail Offside Rear Inner Tie bar/rod ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #6 2015-01-20 11:27

MOT test number 708860025073

Result ✓ Passed

MOT #5 2014-01-23 11:39

MOT test number 446783624062

Result

Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #4 2013-01-16 13:29

MOT test number 739756713073

Result ✓ Passed

Notice Nearside front tyre worn on inner edge

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice All tyres cracking on walls

MOT #3 2012-01-05 15:52 MOT test number 507185202091

Result

Passed

MOT #2 2011-11-10 09:19

MOT test number 405714411328

Result ✓ Passed

MOT #1 2010-11-15 16:03

MOT test number 444749810317

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 6/13



DG57EEX report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	23 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



DG57EEX report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

DG57EEX

report date: 2024-03-28

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-12-14
Last registration	2023-10-23
Complete history	See info



Registration #1	2007-12-14	25 mi
Registration #2	2010-11-15	8.102 mi
Registration #3	2011-11-10	8.899 mi
Registration #4	2012-01-05	9.273 mi
Registration #5	2013-01-16	15.683 mi
Registration #6	2014-01-23	24.236 mi
Registration #7	2015-01-20	33.337 mi
Registration #8	2016-01-21	42.420 mi
Registration #9	2016-01-22	42.422 mi
Registration #10	2017-01-19	49.307 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91,709 esi
Registration #14		11.777 es
Registration #15		91,709 esi
Registration #16		11.777 es
Registration #17		91,709 esi
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.117 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2040 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Kerb weight	1710 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	69 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	561180359FG

CarCheck.co.uk page 13/13