



report date: 2024-03-28

General information

Make	FIAT
Model	500L MULTIJET POP STAR
Colour	Green
Year of manufacture	2014
Top speed	112 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	117 g/km
CO2 label	C







Internet history

Entry 1

Date	2021-05-21
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

**MOT history**

<b>MOT expiry date</b>	2024-06-20
<b>MOT pass rate</b>	64 %
<b>MOT passed</b>	7
<b>Failed MOT tests</b>	4
<b>Total advice items</b>	22
<b>Total items failed</b>	8

<b>MOT #11</b>	2023-06-08 10:35
<b>MOT test number</b>	877626045300
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-06-20

<b>MOT #10</b>	2023-06-05 14:06
<b>MOT test number</b>	401736835052

<b>Result</b>	✗ Failed
---------------	----------

- Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Front Service brake excessively fluctuating (1.2.1 (e))
- Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9** 2022-06-21 10:05**MOT test number** 320677611544**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #8** 2021-05-17 16:04**MOT test number** 162820691676**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #7** 2020-06-09 09:39**MOT test number** 877394706173**Result** ✓ Passed**Advice** Offside Play in steering rack inner joint(s)**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



<b>MOT #6</b>	2020-06-09 09:39
<b>MOT test number</b>	713325246757
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Offside Play in steering rack inner joint(s)
<b>Advice</b>	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Pass with rectification</b>	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

<b>MOT #5</b>	2019-05-28 10:49
<b>MOT test number</b>	182123182695
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

<b>MOT #4</b>	2018-05-28 16:27
<b>MOT test number</b>	289996448102
<b>Result</b>	✓ Passed

<b>MOT #3</b>	2018-05-25 08:41
<b>MOT test number</b>	493405629125
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Rear Service brake binding but not excessively (1.2.1 (f))
<b>Advice</b>	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Fail</b>	Rear Brakes imbalanced across an axle (1.2.1 (b) (i))
<b>Advice</b>	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))



MOT #2	2017-06-03 09:51
MOT test number	384425859633
Result	✓ Passed
Advice	Items removed from driver's view prior to test

MOT #1	2017-05-27 08:11
MOT test number	697854813641
Result	✗ Failed
Advice	Items removed from driver's view prior to test
Fail	Offside Rear Seat belt locking mechanism does not secure or release (5.2.5a)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
20 June 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	367
<b>MOT expiry date</b>	20 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation


<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-06-10
Last registration	2023-06-08
Complete history	<a href="#">See info</a>



Registration #1	2014-06-10	8 mi
Registration #2	2017-05-27	39.290 mi
Registration #3	2017-06-03	39.612 mi
Registration #4	2018-05-25	45.984 mi
Registration #5	2018-05-28	45.984 mi
Registration #6	2019-05-28	50.484 mi
Registration #7	2020-06-09	54.997 mi
Registration #8	2021-06-09	55.277 mi
Registration #9	2021-06-09	55.277 mi
Registration #10	2021-06-09	55.277 mi
Registration #11	2021-06-09	55.277 mi
Registration #12	2021-06-09	55.277 mi
Registration #13	2021-06-09	55.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2018 mm
Height	1667 mm
Length	4147 mm
Wheel base	2612 mm
Kerb weight	1365 kg
Max. allowed weight	1925 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	6946424