





report date: 2024-03-28

General information

| Make | VOLKSWAGEN |
|---------------------|--|
| Model | CADDY C20 TDI HIGHLINE BLUEMOTION TECHNOLOGY |
| Colour | Silver |
| Year of manufacture | 2017 |
| Top speed | 106 mph |
| 0 - 60 mph | 12.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 101 BHP |
|-------------------------|---------------------|
| Max. torque | 250 Nm at 2.500 rpm |
| Engine capacity | 1.968 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 47.1 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 54.3 mpg |
| CO2 emission | 123 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date 2021-08-21

Pictures 22

Listing price <u>View report</u>









source: heycar.co.uk

Entry 1

Date 2021-07-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



| MC | TC | history | |
|----|----|---------|--|
|----|----|---------|--|

| MOT expiry date | 2024-08-01 |
|--------------------|------------|
| MOT pass rate | 63 % |
| MOT passed | 5 |
| Failed MOT tests | 3 |
| Total advice items | 2 |
| Total items failed | 2 |

| MOT #8 | 2023-08-02 13:49 |
|------------------|------------------|
| MOT test number | 414455854293 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-01 |

| MOT #7 | | 2023-08-02 13:49 |
|-------------------------|---|------------------|
| MOT test number | | 558487149986 |
| Result | | × Failed |
| Pass with rectification | Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) | |

| MOT #6 | 2022-09-12 15:43 |
|-----------------|------------------|
| MOT test number | 566365566064 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2021-09-07 16:15 |
| MOT test number | 653017554642 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2021-03-22 11:45 |
| MOT test number | 240215656500 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



× Failed

MOT #3 2021-03-22 11:45

MOT test number 372574247920

Result

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #2 2020-03-13 11:45

MOT test number 130499517643

Result ✓ Passed

MOT #1 2020-03-11 15:54

MOT test number 947595792807

Result X Failed

Minor Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

MAJOR Offside Stop lamp(s) not working (4.3.1 (a) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check



| lax status | Valid until 1 July |
|------------------|--------------------|
| Days left | 62 |
| MOT expiry date | 1 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28


Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

| Date | |
|----------|--|
| Category | |
| Туре | |

| Damage 2 | |
|----------|--|
| Date | |
| Category | |
| | |



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



More info >

Owner history

| For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report here . | | |
|---|-------------|--|
| | | |
| *************************************** | | |
| *************************************** | | |
| | | |
| *************************************** | | |
| | | |
| | More info > | |
| Plate changes | | |
| See in this check if this VOLKSWAGEN had different number plates. | | |
| Number of plates | , | |
| Current registration | NIK NIK | |
| Plate since | | |
| Current registration | UK NE | |
| Plate since | | |

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 11 |
| First mileage registration | 2017-03-29 |
| Last registration | 2023-08-02 |
| Complete history | See info |



| Registration #1 | 2017-03-29 | 17 mi |
|------------------|------------|-----------|
| Registration #2 | 2020-03-11 | 38.704 mi |
| Registration #3 | 2020-03-13 | 38.704 mi |
| Registration #4 | 2021-03-22 | 42.172 mi |
| Registration #5 | 2021-03-22 | 42.172 mi |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | *** |
|----------------|-----------------|
| Adult | 84% |
| Children | 78% |
| Pedestrian | 58% |
| Safety systems | 68% |
| Overall rating | 74% |
| Video | see crash video |



Dimensions & weight

| Width | 2062 mm |
|---------------------|---------|
| Height | 1836 mm |
| Length | 4876 mm |
| Kerb weight | 1594 kg |
| Max. allowed weight | 2299 kg |

Additional information

| Fuel tank capacity | 60 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 2 |

CarCheck.co.uk page 11/11

Engine number

DFSD212556