





report date: 2024-03-28

#### General information

Make	NISSAN
Model	PRIMERA SVE
Colour	Red
Year of manufacture	2004
Top speed	113 mph
Gearbox	4 speed automatic

# Engine & fuel consumption

Power	114 BHP
Max. torque	163 Nm at 4.000 rpm
Engine capacity	1.769 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	42.8 mpg
Consumption combined	35.3 mpg
CO2 emission	192 g/km
CO2 label	J



CarCheck.co.uk page 1/14



# Internet history


#### Entry 1

Date	2021-12-03
Pictures	10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



# MOT history

MOT expiry date	2024-01-18
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	10
Total items failed	7

MOT #20		2023-01-19 10:17
MOT test	number	974230590609
Result		<b>✓</b> Passed
Next expi	ry date	2024-01-18
Advice	Brake disc worn, pitted or scored, but not seriously weakened Both fro	nt (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Brake disc worn, pitted or scored, but not seriously weakened Both rea	ar (1.1.14 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge VERY LOW	(5.2.3 (e))

CarCheck.co.uk page 3/14



**MOT #19** 2023-01-18 09:41

**MOT test number** 391430464055

Result X Failed

Advice Brake disc worn, pitted or scored, but not seriously weakened Both rear (1.1.14 (a) (ii))

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Nearside Front Tyre worn close to legal limit/worn on edge VERY LOW (5.2.3 (e))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Offside Side repeater incorrect colour (4.4.3 (a))

Advice Brake disc worn, pitted or scored, but not seriously weakened Both front (1.1.14 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Nearside Side repeater incorrect colour (4.4.3 (a))

**MOT #18** 2021-12-02 14:05

**MOT test number** 682909063513

Result \rightarrow Passed

**MOT #17** 2020-12-11 12:50

**MOT test number** 245180525374

**Result** ✓ Passed

**MOT #16** 2019-12-11 11:31

**MOT test number** 134242551498

**Result** 
✓ Passed

CarCheck.co.uk page 4/14



MOT #15 2018-12-13 12:46

**MOT test number** 625345608102

MOT #14 2017-12-11 11:55

**MOT test number** 127515342028

Result 

Passed

MOT #13 2016-12-15 12:57

**MOT test number** 919091782633

**Result** 
✓ Passed

MOT #12 2015-12-10 10:49

**MOT test number** 233765967699

**Result** ✓ Passed

**MOT #11** 2014-12-08 15:01

**MOT test number** 806742444384

**MOT #10** 2014-12-08 15:01

**MOT test number** 985912344337

**Result** X Failed

**Pass with rectification** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach

the ply or cords (4.1.D.1a)

MOT #9 2013-12-02 10:54

MOT test number 716356033390

CarCheck.co.uk page 5/14



Result

FEO4TXJ report date: 2024-03-28

✓ Passed

MOT #8	2012-12-21 10:53
MOT test number	995476152363
Result	✓ Passed
MOT #7	2011-12-09 14:53
MOT test number	516643441390
Result	✓ Passed
MOT #6	2011-01-11 10:49
MOT test number	168621111456
Result	✓ Passed
MOT #5	2010-01-12 12:07
MOT test number	224532510066
	* * F=!!=-!
Result	<b>★</b> Failed
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification  MOT #4	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)  2010-01-12 12:07
Pass with rectification  MOT #4  MOT test number	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)  2010-01-12 12:07  341462810001
Pass with rectification  MOT #4  MOT test number	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)  2010-01-12 12:07  341462810001
Pass with rectification  MOT #4  MOT test number  Result	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)  2010-01-12 12:07  341462810001  ✓ Passed
Pass with rectification  MOT #4  MOT test number  Result  MOT #3	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)  2010-01-12 12:07  341462810001  ✓ Passed  2009-01-13 12:09
Pass with rectification  MOT #4  MOT test number  Result  MOT #3  MOT test number  Result	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)  2010-01-12 12:07  341462810001  ✓ Passed  2009-01-13 12:09  591613919019  ✓ Passed
Pass with rectification  MOT #4  MOT test number  Result  MOT #3  MOT test number	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)  2010-01-12 12:07  341462810001  ✓ Passed  2009-01-13 12:09  591613919019

CarCheck.co.uk page 6/14



MOT #1 2007-03-08 14:29

**MOT test number** 190347767493

**Result** ✓ Passed

CarCheck.co.uk page 7/14



#### Tax & MOT check



Tax expired: 15 November 2023

# X MOT

Expired: 18 January 2024

Tax status	Expired at 15 November 2023
Days left	166 days too late
MOT expiry date	18 January 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 8/14



#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

e when miscory		
For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		I
THE STATE OF THE S		
***************************************		
	More info	>
Plate changes		
See in this check if this NISSAN had different number plates.		
Number of plates		,
Current registration	NK NA	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



# Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2004-03-30
Last registration	2023-01-19
Complete history	See info



Registration #1	2004-03-30	27 mi
Registration #2	2007-03-08	27.822 mi
Registration #3	2008-01-11	32.685 mi
Registration #4	2009-01-13	35.229 mi
Registration #5	2010-01-12	37.692 mi
Registration #6	2011-01-11	40.166 mi
Registration #7	2011-12-09	42.067 mi
Registration #8	2012-12-21	43.707 mi
Registration #9	2013-12-02	45.201 mi
Registration #10	2014-12-08	46.888 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		91,709 esi
Registration #14		11.777 es
Registration #15		9.79 es
Registration #16		11.777 es
Registration #17		9.79 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.117 es

More info >

CarCheck.co.uk page 13/14



### Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1760 mm
Height	1488 mm
Length	4567 mm
Wheel base	2680 mm
Kerb weight	1386 kg

# Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	335856 page 14/14