





report date: 2024-03-29

## General information

Make	LAND ROVER	
Model	DEFENDER TD HARD TOP	
Colour	White	
Year of manufacture	2013	
Top speed	90 mph	
0 - 100 km/h	15.8 seconds	
0 - 60 mph	14.7 seconds	
Gearbox	6 speed Manual	

## Engine & fuel consumption

Power	90 kW / 123 HP / 122 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	31.0 mpg
Consumption combined	28.3 mpg
CO2 emission	266 g/km
CO2 label	М



CarCheck.co.uk page 1/14



# Internet history

### Entry 1

Date	2021-05-26
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/14



# MOT history

MOT expiry date	2024-12-06
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	31
Total items failed	10

MOT #12	2023-12-07 09:57
MOT test number	829014478067
Result	✓ Passed
Next expiry date	2024-12-06
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #11	2022-11-24 10:14
MOT test number	137320836393
Result	✓ Passed
MOT #10	2021-07-08 10:17
MOT test number	761511924842
Result	✓ Passed
MOT #9	2020-02-19 09:48
MOT test number	280977867062
Result	✓ Passed
Advice Front Number plate damaged	
Advice All four tyres miss shaping	

CarCheck.co.uk page 3/14



MOT test number

Fail Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))

Advice Front Number plate damaged

MOT #7

MOT test number

Result

Advice Offside Front Seat belt slightly damaged (7.1.2 (b) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

CarCheck.co.uk page 4/14



MOT #6 2019-01-31 10:27

MOT test number 373822091072

Result × Failed

Advice Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Fail** Nearside Headlamp aim too high (4.1.2 (a))

**Advice** Offside Front Seat belt slightly damaged (7.1.2 (b) (i))

Fail Nearside Rear Lower Shock absorbers has an excessively worn bush (5.3.2 (c))

Advice Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**Fail** Offside Headlamp aim too high (4.1.2 (a))

**Advice** Offside Front Tyre miss shaped and wearing inner edge

**Fail** Offside Rear Lower Shock absorbers has an excessively worn bush (5.3.2 (c))

**Fail** Offside Front Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #5 2018-02-28 17:08

MOT test number 364054863812

Result / Passed

**Advice** Nearside front washer partly blocked

Advice Offside mirror mounting poor/repaired

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

**Advice** Rear number plate light deteriorated

CarCheck.co.uk page 5/14



**MOT #4** 2017-03-01 11:30

**MOT test number** 916018918140

**Advice** Nearside wiper poor

Advice All tyres except nearside front have cuts / damaged

**Advice** Offside non standard wing mirror with poor security

Advice Handbrake travel on limit

Advice Offside number plate lamp bulb not working but nearside provides adequate illumination

MOT #3 2017-03-01 11:30

**MOT test number** 861627558976

Result × Failed

Advice Offside number plate lamp bulb not working but nearside provides adequate illumination

**Advice** Nearside wiper poor

**Pass with rectification** Nearside Headlamp aim too far to the right (1.8)

**Advice** All tyres except nearside front have cuts / damaged

**Advice** Offside non standard wing mirror with poor security

**Advice** Handbrake travel on limit

**Pass with rectification** Offside Headlamp aim too far to the right (1.8)

MOT #2 2016-01-05 09:49

MOT test number 865108996813

**Result** 
✓ Passed

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 6/14



MOT #1 2016-01-05 09:49

MOT test number 697885015650

Result × Failed

Pass with rectification Offside Front Front position lamp(s) not working (1.1.A.3b)

**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 7/14



# Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	6 December 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 8/14



### Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date
Category
Type

Damage 2

Date

Category

**Type** 



#### Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



### Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner	بمنحاء أحا
UWNER	nistary
OVVIICI	IIISCUIV

For how long did the current and previous owner(s) have this LAND ROVER? How many or ROVER have? Check it in the premium report and see all owner registrations. Download to	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 11/14



### Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 12/14



# Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-01-25
Last registration	2023-12-07
Complete history	See info



Registration #1	2013-01-25	8 mi
Registration #2	2016-01-05	37.208 mi
Registration #3	2016-01-05	37.208 mi
Registration #4	2017-03-01	50.349 mi
Registration #5	2017-03-01	50.349 mi
Registration #6	2018-02-28	59.429 mi
Registration #7	2019-01-31	66.766 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.177 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 13/14



# Dimensions & weight

Width	1992 mm
Height	2182 mm
Length	4040 mm
Wheel base	2360 mm
Kerb weight	1759 kg
Max. allowed weight	2505 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Number of axles	2
Engine number	130502003651DT224

CarCheck.co.uk page 14/14