





report date: 2024-03-28

General information

| Make | VOLVO | |
|---------------------|----------------------|--|
| Model | XC40 D3 MOMENTUM PRO | |
| Colour | White | |
| Year of manufacture | 2018 | |
| Top speed | 124 mph | |
| 0 - 60 mph | 9.8 seconds | |
| Gearbox | 8 speed automatic | |

Engine & fuel consumption

| Power | 148 BHP |
|------------------------|---------------------|
| Max. torque | 320 Nm at 1.750 rpm |
| Engine capacity | 1.969 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption combined | 2.8 mpg |
| CO2 emission | 131 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/11



BX68OWW

report date: 2024-03-28

Internet history


Entry 1

Date 2021-10-04

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-10-12 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 10 |
| Total items failed | 1 |

| MOT #4 | | 2023-10-03 14:28 |
|-----------|--|------------------|
| MOT test | number | 730131928051 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-10-12 |
| Advice | Nearside Front Tyre damaged on outer tyre wall | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Rear Tyre damaged on outer tyre wall | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Tyre damaged on outer tyre wall | |

| MOT #3 | | 2023-10-03 11:32 |
|----------|--|------------------|
| MOT test | number | 242769615095 |
| Result | | × Failed |
| Advice | Nearside Front Tyre damaged on outer tyre wall | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Rear Tyre damaged on outer tyre wall | |
| Fail Re | ear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |
| Advice | Offside Front Tyre damaged on outer tyre wall | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

CarCheck.co.uk page 3/11



BX68OWW

report date: 2024-03-28

| MOT #2 | 2022-10-04 12:30 |
|-----------------|------------------|
| MOT test number | 139854947051 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2021-10-13 14:53 |
| MOT test number | 208014690332 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 December |
|------------------|------------------------|
| Days left | 216 |
| MOT expiry date | 12 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|------------|
| Band | Н |
| First licence fee (12 months) | £ 255,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 645,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

BX680WW

report date: 2024-03-28

| For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLV have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u> . | ′ O |
|--|------------|
| | |
| STREET, STREET | |
| | |
| | |
| | |
| THE PERSON NAMED IN COLUMN TO THE PE | |
| | |
| | |
| | |
| More info | > |

Plate changes

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Control info | |

Contact info

More info >

CarCheck.co.uk page 9/11



BX68OWW

report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2018-11-22 |
| Last registration | 2023-10-03 |
| Complete history | See info |



| Registration #1 | 2018-11-22 | 27 mi |
|-----------------|------------|-----------|
| Registration #2 | | 11.777 es |
| Registration #3 | 2021-10-13 | 11.237 mi |
| Registration #4 | | 71,777 66 |
| Registration #5 | | 11,777 es |
| Registration #6 | | 11.777 au |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 97% |
| Children | 87% |
| Pedestrian | 71% |
| Safety systems | 76% |
| Overall rating | 86% |
| Video | see crash video |



Dimensions & weight

| Width | 1910 mm |
|---------------------|---------|
| Height | 1658 mm |
| Length | 4425 mm |
| Kerb weight | 1603 kg |
| Max. allowed weight | 2180 kg |

Additional information

| Fuel tank capacity | 54 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles CarCheck.co.uk | 2 page 11/11 |
| | |

Engine number

2896427