



report date: 2024-03-29

General information

Make	CITROEN
Model	C5 HDI EXCLUSIVE
Colour	Grey
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	154 BHP
Max. torque	379 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-10-20
Pictures	15
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-18
Pictures	15
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #12	2021-02-03 09:33
MOT test number	913108330736
Result	✓ Passed
Next expiry date	2022-02-03
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #11	2021-02-01 13:12
MOT test number	336532092872
Result	✗ Failed
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Fail	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #10	2020-02-04 16:56
MOT test number	239172377911
Result	✓ Passed
Advice	Headlamp washers not working
Advice	Engine oil leak
Advice	Nearside Front wheel arch liner loose

**MOT #9**

2020-01-28 16:06

MOT test number

422114115038

Result**✗ Failed****Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front wheel arch liner loose**Advice** Headlamp washers not working**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Rear Fuel tank leaking (6.1.3 (b) (i))**Advice** Engine oil leak**MOT #8**

2019-01-29 15:31

MOT test number

143932078766

Result**✓ Passed****Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #7**

2018-01-24 09:16

MOT test number

164513450942

Result**✓ Passed****Advice** Oil leak**Advice** Undertrays fitted to vehicle and brake pipes are underneath these trays so brake pipes could not be inspected**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front Nail in tyre**Advice** Engine management light indicates a fault

**MOT #6** 2017-01-10 16:41**MOT test number** 450246918388**Result** ✓ Passed**Advice** Offside Rear Inner Tyre worn close to the legal limit edge (4.1.E.1)**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #5** 2016-09-15 09:50**MOT test number** 829620678279**Result** ✗ Failed**Advice** Offside Rear Inner Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Fail** Nearside Rear Inner Tyre has ply or cords exposed (4.1.D.1b)**Advice** Oil leak**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)**Fail** Offside Rear Stop lamp not working (1.2.1b)**MOT #4** 2015-09-14 15:03**MOT test number** 976638184082**Result** ✓ Passed**Advice** Nail in offside front tyre**MOT #3** 2015-07-06 14:38**MOT test number** 256307485110**Result** ✓ Passed



MOT #2	2014-07-03 17:02
MOT test number	718124284177
Result	✓ Passed

MOT #1	2014-06-26 13:07
MOT test number	139257174155
Result	✗ Failed
Fail	Offside Front Wheel bolt(s) missing (4.2.A.1e)
Fail	Offside Rear Wheel bolt(s) missing (4.2.A.1e)
Fail	Nearside Headlamp cleaning device obviously defective (1.7.2)
Fail	Nearside Front Wheel bolt(s) missing (4.2.A.1e)
Fail	Nearside Rear Wheel bolt(s) missing (4.2.A.1e)
Fail	Driver's seat insecure (6.2.A.1)
Fail	Offside Headlamp cleaning device obviously defective (1.7.2)
Notice	N/s/r tyre wearing on inner edge.



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-03-30
Last registration	2021-02-03
Complete history	See info



Registration #1	2007-03-30	25 mi
Registration #2	2014-06-26	68.657 mi
Registration #3	2014-07-03	68.657 mi
Registration #4	2015-07-06	76.288 mi
Registration #5	2015-09-14	76.436 mi
Registration #6	2016-09-15	106.080 mi
Registration #7	2017-01-10	114.588 mi
Registration #8	2018-01-24	121.906 mi
Registration #9	2019-01-24	121.906 mi
Registration #10	2019-01-24	121.906 mi
Registration #11	2019-01-24	121.906 mi
Registration #12	2019-01-24	121.906 mi
Registration #13	2019-01-24	121.906 mi
Registration #14	2019-01-24	121.906 mi
Registration #15	2019-01-24	121.906 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1805 mm
Height	1715 mm
Length	4645 mm
Wheel base	2670 mm
Kerb weight	1750 kg
Max. allowed weight	2410 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	DZ554009832