





General information

Make	VOLKSWAGEN
Model	CC GT TDI BLUEMOTION TECHNOLOGY DSG
Colour	White
Year of manufacture	2013
Top speed	137 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	130 kW / 177 HP / 175 BHP
Max. torque	380 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	137 g/km
CO2 label	E







Internet history

Entry 1

Date Pictures 2021-11-28

8

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-15
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	15
Total items failed	0

MOT #12	2024-01-12 17:12
MOT test number	276003517320
Result	✓ Passed
Next expiry date	2025-01-15

MOT #11	2024-01-11 14:32	
MOT test number	721931744231	
Result	🗙 Failed	
DANGEROUS Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))		
DANGEROUS Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))		
Advice Offside Front Tyre worn close to legal limit/worn on edge worn on inner ed	lge (5.2.3 (e))	

MOT #10	2023-01-16 14:44
MOT test number	326140915874
Result	✓ Passed





MOT #9	2023-01-09 15:51	
MOT test number	955900879129	
Result	🗙 Failed	
MAJOR Brake performance not tested Due to pads on metal (1.2.1 (g))		
DANGEROUS Nearside Rear Brake pad(s) less than 1.5 mm thick inner pad on metal (1.1.13 (a) (ii))		
Advice Central Non obligatory mirror damaged interior mirror covered		

МОТ #8	2021-12-09 17:17
MOT test number	132836980903
Result	✓ Passed

MOT #7	2021-01-08 15:54
MOT test number	912603234813
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #6	2020-01-09 12:24
MOT test number	246150488105
Result	✓ Passed

MOT #5		2019-12-20 13:15
MOT test	number	287711103264
Result		🗙 Failed
MAJOR	Nearside Headlamp not working on main beam (4.1.1 (a) (ii))	
DANGER	OUS Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
MAJOR	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice (i))	Nearside Tyre has a cut but not deep enough to reach the ply or cords outer	sidewall. (5.2.3 (d)





MOT #4		2018-12-21 12:22
MOT test	number	988157174071
Result		✓ Passed
MOT #3		2018-12-20 12:47
MOT test	number	643861574831
Result		× Failed
MAJOR	Rear Reversing lamp inoperative both not working (4.6.1 (a))	
MAJOR	Rear Rear fog lamp not working (4.5.1 (a) (ii))	
MOT #2		2017-12-08 10:07
MOT test	number	130220508744
Result		✓ Passed
Advice	Front both front tyres wearing on inner and outer edges	

MOT #1	2016-11-15 10:05
MOT test number	276104991913
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 April 2025	✓ MOT Expires: 15 January 2025
Tax status	Valid until 1 April
Days left	337
MOT expiry date	15 January 2025
Full MOT history	<u>See MOT history</u>

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CAT ON
Date	*
Category	AMP
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 =

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ANALY AND A ANALY	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate sites	





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-08-02
Last registration	2024-01-12
Complete history	See info



Registration #1	2013-08-02	11 mi
Registration #2	2016-11-15	32.264 mi
Registration #3	2017-12-08	36.227 mi
Registration #4	2018-12-20	47.933 mi
Registration #5	2018-12-21	47.933 mi
Registration #6	2019-12-20	63.662 mi
Registration #7	2020-01-09	64.617 mi
Registration #8		11.777 est
Registration #8 Registration #9		11.577 est 11.577 est
-		01.000 est 01.000 est 01.000 est
Registration #9		0.000 est 0.000 est 0.000 est 0.000 est
Registration #9 Registration #10		0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #9 Registration #10 Registration #11		0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight	
Width	2090 mm
Height	1421 mm
Length	4902 mm
Wheel base	2710 mm
Kerb weight	1581 kg
Max. allowed weight	2110 kg
Additional information	
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	CFGC517648