





General information	
Make	VOLKSWAGEN
Model	CARAVELLE CARAVELLE 78PS
Colour	Beige
Year of manufacture	1986
Gearbox	-Manual

Engine & fuel consumption

Engine capacity	1.915 cc	0 < 101 A	LABEL UNKNOWN
Fuel type	Petrol	101 - 120 B 121 - 140 E 141 - 165 F	

225+



C896HTT report date: 2024-03-28

Internet history


Entry 1

Date Pictures 2021-08-21

Listing price

View report

7



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-13
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	46
Total items failed	8

MOT #23	2023-06-14 07:49
MOT test number	665280000007
Result	✓ Passed
Next expiry date	2024-06-13
Minor Nearside Registration plate lamp inoperative in the case of multiple la (b) (i))	amps or light sources (4.7.1

MOT #22	2023-06-14 07:49
MOT test number	358528940154
Result	× Failed
Pass with rectification (a))	Nearside Front passenger door cannot be opened from inside the vehicle (6.2.3
Minor (b) (i)) Nearside Registra	ation plate lamp inoperative in the case of multiple lamps or light sources (4.7.1
Pass with rectification (a))	Nearside Front passenger door cannot be opened from outside the vehicle (6.2.3

MOT #21		2021-07-20 15:43
MOT test	number	983039364270
Result		✓ Passed
Advice	Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))	





MOT #20		2021-07-05 08:52
MOT test	number	139049237039
Result		🗙 Failed
MAJOR	Offside Rear Inner Brake pipe excessively corroded (1.1.11 (c))	
Advice	Nearside Rear Exhaust silencer slightly loose clamp missing (8.1.1 (b) (i))	
Advice	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))	
MAJOR (7.1.1 (a) (Nearside Front Seat belt anchorage prescribed area strength or continuity si i))	gnificantly reduced
MAJOR	Offside Headlamp aim too high (4.1.2 (a))	
DANGER	OUS Parking brake efficiency less than 50% of the required value (1.4.2 (a)) (ii))
MAJOR	Offside Front Upper Suspension arm pin or bush excessively worn (5.3.4 (a)	(i))
Advice	Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))	

MOT #19	2020-06-29 14:23
MOT test number	357834021508
Result	✓ Passed
Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))	
Minor (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple lamps or	light sources (4.7.1
Advice Offside Rear Inner Brake pipe corroded, covered in grease or other material	(1.1.11 (c))
Advice Covers obscuring some components	
Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in exercise (5.3.4 (a) (i))	cessive movement
Advice Nearside Rear Inner Brake pipe corroded, covered in grease or other materia	ıl (1.1.11 (c))



C896HTT
report date: 2024-03-28

MOT #18		2019-07-20 08:41
MOT test	number	878706713012
Result		✓ Passed
Advice	Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))	
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps or lig	ght sources (4.7.1
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))	

MOT #17		2019-07-20 08:41
MOT test number		726502621865
Result		× Failed
Minor Nearside Registration plat	e lamp inoperative in the case o	of multiple lamps or light sources (4.7.1
Advice Nearside Front Wheel bea	aring has slight play (5.1.3 (a) (i))
Advice Nearside Rear Wheel bea	ring has slight play (5.1.3 (a) (i)))
Pass with rectification Nearsic	le Rear Stop lamp(s) not working	g (4.3.1 (a) (ii))
Advice Offside Front Wheel bear	ing has slight play (5.1.3 (a) (i))	
Advice Offside Rear Wheel beari	ng has slight play (5.1.3 (a) (i))	

MOT #16	2018-07-17 13:40
MOT test number	375828113729
Result	✓ Passed
Advice Nearside Rear Brake pipe corroded, covered in grease or other material U((c))	NION TO FLEXY (1.1.11
Advice Offside Front Brake pipe corroded, covered in grease or other material SH (1.1.11 (c))	ORT PIPE ON CALIPER
Advice Brake pipe corroded, covered in grease or other material FRONT TO REAR	AT FRONT (1.1.11 (c))





MOT #15		2018-07-06 11:13
MOT test	number	567702229279
Result		🗙 Failed
MAJOR	Offside Rear Brake pipe excessively corroded (1.1.11 (c))	
Advice (1.1.11 (c)	Offside Front Brake pipe corroded, covered in grease or other material SHORT)	PIPE ON CALIPER
Advice	Brake pipe corroded, covered in grease or other material FRONT TO REAR AT	FRONT (1.1.11 (c))
MAJOR significant	Nearside Rear Suspension component mounting prescribed area excessively only reducing structural strength SILL (5.3.6 (a) (i))	corroded
MAJOR	Nearside Rear Brake pipe excessively corroded (1.1.11 (c))	
MAJOR	Offside Rear Brake pipe excessively corroded UNION TO FLEXY (1.1.11 (c))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material UNIO	N TO FLEXY (1.1.11
MAJOR reducing s	Offside Rear Suspension component mounting prescribed area excessively co tructural strength SILL / ARCH (5.3.6 (a) (i))	rroded significantly

MOT #14		2017-06-23 09:54
MOT test	number	352017390165
Result		✓ Passed
Advice	Oil leak	
Advice	Rear wheel bearing has slight play both (2.6.2)	
Advice	Front wheel bearing has slight play both (2.5.A.3c)	

2016-07-12 10:44
734324962518
✓ Passed

MOT #12	2015-06-09 13:48
MOT test number	725540565128
Result	✓ Passed



MOT #1	11	2015-06-09 12:38
MOT te	st number	399390565100
Result		🗙 Failed
Fail	Rear fog lamp tell tale not working (1.3.1b)	
Fail	Nearside Headlamp not working on main beam (1.7.5a)	

MOT #10	2014-06-18 10:42
MOT test number	959039864155
Result	✓ Passed
Notice Rear exhaust tail pipe deteriorated	

MOT #9	2013-06-18 10:55
MOT test number	577749363144
Result	✓ Passed
Advice Nearside Rear wheel bearing has slight play (2.6.2)	

MOT #8	2012-06-25 11:22
MOT test number	805977872137
Result	✓ Passed
Advice Nearside Rear Rear wheel bearing has slight play (2.6.2)	

MOT #7	2011-07-15 10:25
MOT test number	627756691115
Result	✓ Passed

МОТ #6	2010-06-26 10:47
MOT test number	494807270191
Result	✓ Passed







MOT #5	2009-06-24 15:29
MOT test number	462175979143
Result	✓ Passed
MOT #4	2009-06-22 10:51
MOT test number	800343679101
Result	🗙 Failed
Fail Offside Rear wheel bearing has excessive play (2.6.2)	
Fail Headlamp aim too low (1.8)	
Fail Exhaust emissions carbon monoxide content excessive (7.3.B.1a)	


MOT #3	2008-07-22 15:04
MOT test number	803644308297
Result	✓ Passed
Advice Rear wheel bearing has slight play (2.6.2)	

MOT #2	2007-07-07 10:52
MOT test number	382088987139
Result	✓ Passed
MOT #1	2006 07 22 10.30

MOT #1	2006-07-22 10:30
MOT test number	324703006232
Result	✓ Passed



Tax & MOT check







Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	E TO U
Category		Lawe
Туре		
Damage 2		AMPLE
	F	
Date		*
Category		ship.
Туре	100000 W	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	

And a second s	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



C896HTT report date: 2024-03-28

Mileage check

Mileage registrations25First mileage registration1986-06-20Last registration2023-06-14Complete historySee info	Odometer	In miles
Last registration2023-06-14	Mileage registrations	25
-	First mileage registration	1986-06-20
Complete history See info	Last registration	2023-06-14
	Complete history	See info



Registration #1	1986-06-20	24 mi
Registration #2	2006-07-22	56.195 mi
Registration #3	2007-07-07	60.435 mi
Registration #4	2008-07-22	62.824 mi
Registration #5	2009-06-22	65.883 mi
Registration #6	2009-06-24	65.893 mi
Registration #7	2010-06-26	69.251 mi
Registration #8	2011-07-15	73.210 mi
Registration #9	2012-06-25	75.479 mi
Registration #10	2013-06-18	78.472 mi
Registration #11	2014-06-18	82.449 mi
Registration #12	2015-06-09	86.486 mi
Registration #13	2015-06-09	86.491 mi
Registration #14		11.777 esi
Registration #15		11.222 esi
Registration #16		11.777 esi
Registration #17		11.777 esi
Registration #18		11.777 est
Registration #19		11.777 esi
Registration #20		10.200 est
Registration #21		11.777 mi
Registration #21 Registration #22		11.317 est
		11.317 est 11.317 est 11.317 est
Registration #22		10.000 est 10.000 est 10.000 est 10.000 est





Car features

he VOLKSWAGEN factory car options list is only available in the p	premium report.
S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	
View the complete VOLKSWAGEN factory list for this vehicle here.	More info >

Additional information

Engine number

DG095790