



report date: 2024-03-28

General information

Make	VOLVO
Model	V60 D3 INSCRIPTION
Colour	Grey
Year of manufacture	2017
Top speed	130 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	108 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-23
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	8
Total items failed	5

MOT #7	2024-03-18 14:59
MOT test number	606829554748
Result	✓ Passed
Next expiry date	2025-03-23
Advice	Engine and under covers fitted obscuring some parts

MOT #6	2024-03-18 09:34
MOT test number	733038717836
Result	✗ Failed
Pass with rectification	Offside Front Headlamp aim too high (4.1.2 (a))
Fail	Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Engine and under covers fitted obscuring some parts
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #5	2023-03-16 10:24
MOT test number	513661572305
Result	✓ Passed
Advice	Engine and under covers fitted obscuring some parts
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

**MOT #4** 2022-02-25 11:42**MOT test number** 583811291833**Result** ✓ Passed**Advice** Engine and under covers fitted obscuring some**MOT #3** 2022-02-24 15:18**MOT test number** 290723659795**Result** ✗ Failed**Advice** Engine and under covers fitted obscuring some**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #2** 2021-03-24 15:53**MOT test number** 141540630552**Result** ✓ Passed**MOT #1** 2020-09-23 09:49**MOT test number** 949400944115**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
23 March 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	23 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 YS67UKY
Plate since	2024-03-28
Current registration	 YS67UKY
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-12-19
Last registration	2024-03-18
Complete history	See info



Registration #1	2017-12-19	18 mi
Registration #2	2020-09-23	43.732 mi
Registration #3	2021-03-24	45.876 mi
Registration #4	2022-02-24	57.736 mi
Registration #5		
Registration #6		
Registration #7		
Registration #8		
Registration #9		

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1857 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1439 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1997496