



report date: 2024-03-28

General information

Make	FIAT
Model	QUBO MULTIJET DYNAMIC
Colour	Silver
Year of manufacture	2009
Top speed	97 mph
0 - 60 mph	16.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	76.3 mpg
Consumption combined	64.2 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-07-05
Pictures	18
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-24
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	45
Total items failed	7

MOT #19	2024-04-25 11:04
MOT test number	824597404331
Result	✓ Passed
Next expiry date	2025-04-24

MOT #18	2024-04-25 08:00
MOT test number	428285994689
Result	✗ Failed
MAJOR	Horn not working (7.7 (a))
MAJOR	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))
MAJOR	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #17	2023-04-25 10:12
MOT test number	658026611256
Result	✓ Passed
Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #16** 2023-04-24 09:31**MOT test number** 933421793498**Result** ✗ Failed**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #15** 2022-04-06 09:28**MOT test number** 503466198828**Result** ✓ Passed**MOT #14** 2021-04-06 11:13**MOT test number** 508945843590**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge both front tyres worn smooth on inner edges (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Centre and rear exhaust rubber mountings deteriorated**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Coil spring corroded nearside front and offside front (5.3.1 (b) (i))**Advice** Front fog lamps inoperative**MOT #13** 2020-06-17 10:15**MOT test number** 502160520159**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)

**MOT #12** 2020-06-16 08:09**MOT test number** 167045667246**Result** ✗ Failed**MAJOR** Nearside Rear Direction indicator adversely affected by the operation of another lamp (4.4.3 (b))**Advice** Play in steering rack inner joint(s)**MAJOR** Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))**MAJOR** Nearside Rear Direction indicator adversely affected by the operation of another lamp (4.4.3 (b))**MAJOR** Offside Rear All position lamps adversely affected by the operation of another lamp (4.2.3 (c))**MOT #11** 2019-12-11 12:32**MOT test number** 763514982568**Result** ✓ Passed**MOT #10** 2019-01-19 08:40**MOT test number** 284805805943**Result** ✓ Passed**MOT #9** 2017-11-28 11:55**MOT test number** 721588668173**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #8**

2017-11-20 16:43

MOT test number

546642661790

Result**✗ Failed****Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)**Fail** Offside Headlamp aim too high (1.8)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Fuel system component leaking oil leaking on sump (7.2.3)**Fail** Nearside Headlamp aim too high (1.8)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Fuel system component leaking on engin (7.2.3)**MOT #7**

2016-11-08 08:39

MOT test number

642458845761

Result**✓ Passed****Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Oil leak**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6**

2016-11-07 16:21

MOT test number

871936667311

Result

✗ Failed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Oil leak**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5**

2015-11-02 12:07

MOT test number

774265080944

Result

✓ Passed

Advice Nearside windscreen wiper is split on both ends**Advice** Both rear tyres are slightly worn on edges**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front slightly worn (3.5.1i)**Advice** Both headlamp aims on max high limit**Advice** Oil leak**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4**

2014-10-23 15:50

MOT test number

518306594274

Result

✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Front brake pads 75% worn**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #3	2013-10-23 11:00
MOT test number	337956793246
Result	✓ Passed

MOT #2	2012-11-05 15:18
MOT test number	597070612337
Result	✓ Passed
<div>Notice Oil leak</div>	

MOT #1	2012-11-05 11:56
MOT test number	375470812395
Result	✗ Failed
<div>Fail Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)</div> <div>Notice Oil leak</div>	



Tax & MOT check

X

Untaxed

Tax expired:
1 August 2023

✓

MOT

Expires:
24 April 2025

Tax status	Expired at 1 August 2023
Days left	272 days too late
MOT expiry date	24 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	WJ59XGN
Plate since	2019-09-28
Current registration	WJ59XGN
Plate since	2019-09-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-09-04
Last registration	2024-04-25
Complete history	See info



Registration #1	2009-09-04	22 mi
Registration #2	2012-11-05	26.446 mi
Registration #3	2012-11-05	26.446 mi
Registration #4	2013-10-23	35.164 mi
Registration #5	2014-10-23	44.165 mi
Registration #6	2015-11-02	55.673 mi
Registration #7	2016-11-07	64.967 mi
Registration #8	2016-11-08	64.967 mi
Registration #9	2017-11-20	72.951 mi
Registration #10	2017-11-28	72.952 mi
Registration #11	2019-01-19	73.618 mi
Registration #12	2019-01-20	73.618 mi
Registration #13	2019-01-20	73.618 mi
Registration #14	2019-01-20	73.618 mi
Registration #15	2019-01-20	73.618 mi
Registration #16	2019-01-20	73.618 mi
Registration #17	2019-01-20	73.618 mi
Registration #18	2019-01-20	73.618 mi
Registration #19	2019-01-20	73.618 mi
Registration #20	2019-01-20	73.618 mi
Registration #21	2019-01-20	73.618 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1716 mm
Height	1735 mm
Length	3959 mm
Wheel base	2513 mm
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

3029472