



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	C C320 CDI SPORT
Colour	Black
Year of manufacture	2009
Top speed	154 mph
0 - 60 mph	6.9 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 1.600 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	27.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.7 mpg
CO2 emission	201 g/km
CO2 label	K







Internet history

Entry 2



Date	2021-07-06
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-05-25
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

**MOT history**

<b>MOT expiry date</b>	2023-07-15
<b>MOT pass rate</b>	85 %
<b>MOT passed</b>	11
<b>Failed MOT tests</b>	2
<b>Total advice items</b>	15
<b>Total items failed</b>	4

**MOT #13** 2021-06-02 10:56**MOT test number** 866498491045**Result** ✓ Passed**Next expiry date** 2022-06-20

**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #12** 2020-06-12 12:35**MOT test number** 444091022473**Result** ✓ Passed**MOT #11** 2020-06-10 09:01**MOT test number** 653187350794**Result** ✗ Failed

**Fail** Nearside Front Suspension arm ball joint excessively worn front (5.3.4 (a) (i))

**Advice** Offside Front Suspension arm ball joint has slight play front (5.3.4 (a) (i))

**MOT #10** 2019-06-14 13:21**MOT test number** 738596641757**Result** ✓ Passed

**MOT #9** 2018-06-19 08:57**MOT test number** 507614444009**Result** ✓ Passed**Advice** Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #8** 2017-06-21 10:46**MOT test number** 231891673859**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2016-06-14 15:24**MOT test number** 228857312682**Result** ✓ Passed**MOT #6** 2015-09-19 10:37**MOT test number** 352864260015**Result** ✓ Passed**MOT #5** 2014-08-29 17:57**MOT test number** 105601744233**Result** ✓ Passed**MOT #4** 2013-09-09 15:52**MOT test number** 309772953485**Result** ✓ Passed

**MOT #3** 2013-08-07 14:48**MOT test number** 167669213234**Result** ✓ Passed

- Advice** Offside Inner Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Inner Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #2** 2013-08-07 12:51**MOT test number** 118449913200**Result** ✗ Failed

- Advice** Nearside Inner Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Inner Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Inner Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Rear Mechanical brake component has restricted free movement (3.5.1k)
- Advice** Nearside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #1** 2012-09-07 17:58**MOT test number** 586921252284**Result** ✓ Passed



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2023-03-29
Current registration	 <b>XXXXXX</b>
Plate since	2023-03-29

More info >





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-06-26
Last registration	2021-06-02
Complete history	<a href="#">See info</a>



Registration #1	2009-06-26	21 mi
Registration #2	2012-09-07	57.199 mi
Registration #3	2013-08-07	69.097 mi
Registration #4	2013-08-07	69.097 mi
Registration #5	2013-09-09	69.418 mi
Registration #6	2014-08-29	72.907 mi
Registration #7	2015-09-19	76.362 mi
Registration #8	2016-06-14	78.470 mi
Registration #9	2016-06-14	78.470 mi
Registration #10	2016-06-14	78.470 mi
Registration #11	2016-06-14	78.470 mi
Registration #12	2016-06-14	78.470 mi
Registration #13	2016-06-14	78.470 mi
Registration #14	2016-06-14	78.470 mi
Registration #15	2016-06-14	78.470 mi
Registration #16	2016-06-14	78.470 mi

More info >



Dimensions & weight

Width	1770 mm
Height	1447 mm
Length	4581 mm
Wheel base	2760 mm
Max. allowed weight	2185 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64296040806791