





report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 THP DSPORT S/S
Colour	Grey
Year of manufacture	2015
Top speed	118 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	163 BHP
Max. torque	240 Nm at 1.400 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history


Entry 2

Date 2022-01-03

Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk


Entry 1

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2024-11-29
MOT pass rate	100 %
MOT passed	7
Failed MOT tests	0
Total advice items	20
Total items failed	0

MOT #7		2023-11-30 15:23
MOT test	number	176879772462
Result		✓ Passed
Next expi	ry date	2024-11-29
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Advice Front Brake disc worn, pitted or scored, but not seriously weakened Bothsides (1.1.14 (a) (ii))	
Advice	Advice Rear Brake disc worn, but not excessively Bothsides (1.1.14 (a) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Play in steering rack inner joint(s)	
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #6		2023-01-13 13:42
MOT test	number	644515405260
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii	i))
Advice	Nearside Front Play in steering rack inner joint(s)	
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 205/45/17 (5.2.3 (e))	
Advice	Offside Front Outer Tyre slightly damaged wall (5.2.3 (d) (ii))	

MOT #5	2022-01-17 14:22
MOT test number	941773069123
Result	✓ Passed
MOT #4	2021-09-07 07:16
MOT test number	126938332089
Result	✓ Passed

MOT #3	2020-09-08 08:09
MOT test number	366830677091
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 4/11



report date: 2024-03-28

MOT test number

686048410162

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1

MOT test number

727260731243

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	IK NE
Plate since	
Current registration	UK NEZ
Finite since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-04-30
Last registration	2023-11-30
Complete history	See info



Registration #1	2015-04-30	29 mi
Registration #2	2018-04-23	47.776 mi
Registration #3	2019-04-23	66.568 mi
Registration #4	2020-09-08	82.806 mi
Registration #5	2021-09-07	87.194 mi
Danishastian #C		
Registration #6		
Registration #7		11.777 mg
		11.777 mg
Registration #7		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1140 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FJCB2191281

CarCheck.co.uk page 11/11