



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK 200 KOMPRESSOR
Colour	Silver
Year of manufacture	2006
Top speed	140 mph
0 - 60 mph	8.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	42.2 mpg
Consumption combined	32.1 mpg
CO2 emission	221 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-07-28
Pictures	22
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-07
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	18
Total items failed	15

MOT #21	2023-07-31 14:45
MOT test number	163616744532
Result	✓ Passed
Next expiry date	2024-08-07
Advice	Rear Brake pipe corroded, covered in grease or other material x2 (1.1.11 (c))
Advice	Advise under covers fitted time of test

MOT #20	2023-07-31 09:29
MOT test number	863381531316
Result	✗ Failed
Advice	Advise under covers fitted time of test
Fail	Offside Headlamp aim too low (4.1.2 (a))
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Rear Brake pipe corroded, covered in grease or other material x2 (1.1.11 (c))

MOT #19	2022-08-08 11:33
MOT test number	765554538277
Result	✓ Passed

**MOT #18** 2021-08-03 15:04**MOT test number** 270542050252**Result** ✓ Passed**MOT #17** 2020-09-25 09:33**MOT test number** 824870281213**Result** ✓ Passed**MOT #16** 2020-09-09 08:54**MOT test number** 676524460282**Result** ✗ Failed**Fail** Front Windscreen wiper not working (3.4 (a))**Fail** Horn not working (7.7 (a) (ii))**MOT #15** 2019-09-24 13:01**MOT test number** 227705401868**Result** ✓ Passed**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #14** 2019-09-24 13:01**MOT test number** 265690951614**Result** ✗ Failed**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Pass with rectification** Horn not working (7.7 (a) (ii))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Pass with rectification** Front Windscreen wiper not working (3.4 (a))**Pass with rectification** Offside Rear Position lamp showing white light to the rear lens cracked (4.2.3 (a) (ii))

**MOT #13** 2018-10-05 12:50**MOT test number** 521360778333**Result** ✓ Passed**Minor** Offside Rear Position lamp incorrect colour hole in lense (4.2.3 (a) (i))**MOT #12** 2018-10-04 12:02**MOT test number** 384380878715**Result** ✗ Failed**Minor** Offside Rear Position lamp incorrect colour hole in lense (4.2.3 (a) (i))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #11** 2017-08-14 09:35**MOT test number** 443574224920**Result** ✓ Passed**MOT #10** 2016-08-04 10:51**MOT test number** 185116170143**Result** ✓ Passed**Advice** Nearside Front Lower suspension bush**MOT #9** 2015-09-02 12:01**MOT test number** 398069041084**Result** ✓ Passed**MOT #8** 2014-08-20 11:51**MOT test number** 586442634235**Result** ✓ Passed

**MOT #7** 2013-08-22 14:16**MOT test number** 769374133218**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2012-08-30 08:56**MOT test number** 167513642229**Result** ✓ Passed**MOT #5** 2011-09-09 09:03**MOT test number** 545892051294**Result** ✓ Passed**MOT #4** 2010-09-28 15:50**MOT test number** 944701970252**Result** ✓ Passed**Notice** Oil leak poss rear main**Notice** Rear pads 6-8k**MOT #3** 2010-09-28 15:28**MOT test number** 901271070276**Result** ✗ Failed**Notice** Rear pads 6-8k**Fail** Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Notice** Oil leak poss rear main**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



MOT #2	2009-10-07 10:29
MOT test number	221770089282
Result	✓ Passed

MOT #1	2009-10-06 14:42
MOT test number	962769879254
Result	✗ Failed
<div><div>Fail</div> Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)</div> <div><div>Fail</div> Rear Exhaust has a major leak of exhaust gases (7.1.2)</div> <div><div>Advice</div> Offside Front Brake pad(s) wearing thin (3.5.1g)</div> <div><div>Fail</div> Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)</div> <div><div>Advice</div> Nearside Front Brake pad(s) wearing thin (3.5.1g)</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
7 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	7 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 WV56WSF
Plate since	2019-06-29
Current registration	 WV56WSF
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-10-06
Last registration	2023-07-31
Complete history	See info



Registration #1	2006-10-06	15 mi
Registration #2	2009-10-06	49.016 mi
Registration #3	2009-10-07	49.016 mi
Registration #4	2010-09-28	60.280 mi
Registration #5	2010-09-28	60.280 mi
Registration #6	2011-09-09	64.438 mi
Registration #7	2012-08-30	65.945 mi
Registration #8	2013-08-22	67.471 mi
Registration #9	2014-08-20	68.830 mi
Registration #10	2015-09-02	69.943 mi
Registration #11	2016-08-04	70.741 mi
Registration #12	2017-08-14	71.724 mi
Registration #13	2018-08-14	72.707 mi
Registration #14	2019-08-14	73.690 mi
Registration #15	2020-08-14	74.673 mi
Registration #16	2021-08-14	75.656 mi
Registration #17	2022-08-14	76.639 mi
Registration #18	2023-08-14	77.622 mi
Registration #19	2024-08-14	78.605 mi
Registration #20	2025-08-14	79.588 mi
Registration #21	2026-08-14	80.571 mi
Registration #22	2027-08-14	81.554 mi
Registration #23	2028-08-14	82.537 mi

More info >



Dimensions & weight

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1390 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27194430812218