





report date: 2024-03-28

General information

Make	CITROEN
Model	RELAY 35 L3H2 ENTERPRISE BLUEHDI
Colour	White
Year of manufacture	2017
Top speed	92 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	45.6 mpg
CO2 emission	163 g/km
CO2 label	G



CarCheck.co.uk page 1/10



Internet history

Entry 2

Date 2021-06-24

Pictures 31

Listing price <u>View report</u>









source: heycar.co.uk

Entry 1

Date	2021-06-06
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/10



MOT history

MOT expiry date	2023-09-05
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	11
Total items failed	1

MOT #5		2024-02-23 09:36
MOT test	number	387318368788
Result		≍ Failed
MAJOR	Offside Front Headlamp aim projected beam image is obviously incorrect	ct (4.1.2 (c))
MAJOR	Offside Registration plate lamp inoperative in the case of a single lamp	or all lamps (4.7.1 (b) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
DANGER	OUS Front Brakes imbalanced across an axle by more than 50% (1.2.1	L (b) (ii))
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))	
Advice	Front Lower Power steering pipe/hose insecure	
MAJOR (ii))	Nearside Registration plate lamp inoperative in the case of a single lam	p or all lamps (4.7.1 (b)
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2022-09-06 15:38
MOT test number	632571520403
Result	✓ Passed

CarCheck.co.uk page 3/10



✓ Passed

MOT #3 2022-09-06 15:38

MOT test number 346120815929

Result X Failed

Pass with rectification

Result

Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #2 2021-07-06 10:10

MOT test number 714048890744

Advice Offside Rear lamp lens damaged

Minor Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Offside Front Power steering pipe lower mount broken

MOT #1 2020-08-21 09:35

MOT test number 397996955396

CarCheck.co.uk page 4/10



LG67FVL

report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



LG67FVL

More info >

report date: 2024-03-28

Owner history For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this CITROEN had different number plates. ober of plates furthe scinors

CarCheck.co.uk page 7/10



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-25
Last registration	2024-02-23
Complete history	See info



Registration #1	2017-09-25	27 mi
Registration #2	2020-08-21	84.551 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.117 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 9/10



Safety ratings

NCAP rating	大大大 大大
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Dimensions & weight

Width	2508 mm
Height	2524 mm
Length	5998 mm
Kerb weight	1975 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	DYZZ4006301

CarCheck.co.uk page 10/10