



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 SE SPORT
Colour	Blue
Year of manufacture	2008
Top speed	134 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.2 mpg
CO2 emission	195 g/km
CO2 label	J







Internet history

Entry 1

Date	2022-01-22
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-02
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	45
Total items failed	4

MOT #15	2023-11-03 11:07
MOT test number	517227120216
Result	✓ Passed
Next expiry date	2024-11-02
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear sub frame corroded



MOT #14

2023-01-27 17:55

MOT test number

492816384474

Result

✓ Passed

- Advice

Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Offside Rear Nail in tyre
- Advice

Offside Front Tyre worn close to legal limit/worn on edge wearing inner edge (5.2.3 (e))
- Advice

Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice

Exhaust corroded
- Advice

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Nearside Rear Tyre worn close to legal limit/worn on edge wearing edges perishing (5.2.3 (e))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge wearing edges close to legal limit (5.2.3 (e))
- Advice

Unable to check full length of outer sills due to covers
- Advice

Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #13**

2023-01-24 14:51

MOT test number

530409266922

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing inner edge (5.2.3 (e))
- Fail** Suspension arm pin or bush excessively worn offside rear trailing (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Exhaust corroded
- Fail** Suspension arm pin or bush excessively worn nearside rear trailing (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge wearing edges perishing (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing edges close to legal limit (5.2.3 (e))
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Rear Nail in tyre
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Unable to check full length of outer sills due to covers
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12

2021-11-03 15:03

MOT test number

197605962937

Result**✓ Passed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2020-10-24 09:21**MOT test number** 659365799711**Result** ✓ Passed**MOT #10** 2019-05-01 13:02**MOT test number** 142316507256**Result** ✓ Passed**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #9** 2019-05-01 13:02**MOT test number** 602750012298**Result** ✗ Failed**Pass with rectification** Nearside Rear Coil spring corroded so that its cross sectional area is reduced and seriously weakened (5.3.1 (b) (i))**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Offside Rear Coil spring corroded so that its cross sectional area is reduced and seriously weakened (5.3.1 (b) (i))**Advice** Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #8** 2018-05-02 16:51**MOT test number** 100622895614**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit also minor cracks in wall (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit also minor cracks in wall (4.1.E.1)

**MOT #7** 2017-05-08 14:13**MOT test number** 426325153098**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #6** 2016-05-10 16:18**MOT test number** 439996279563**Result** ✓ Passed**MOT #5** 2015-05-08 12:08**MOT test number** 165258825114**Result** ✓ Passed**MOT #4** 2014-05-02 09:08**MOT test number** 747392024105**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2013-05-01 17:51**MOT test number** 935891623125**Result** ✓ Passed



MOT #2	2012-05-04 15:41
MOT test number	466435122180
Result	✓ Passed
MOT #1	2011-05-19 09:53
MOT test number	785549031114
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
2 November 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	2 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-05-22
Last registration	2023-11-03
Complete history	See info



Registration #1	2008-05-22	6 mi
Registration #2	2011-05-19	27.938 mi
Registration #3	2012-05-04	31.320 mi
Registration #4	2013-05-01	34.801 mi
Registration #5	2014-05-02	39.027 mi
Registration #6	2015-05-08	44.811 mi
Registration #7	2016-05-10	50.307 mi
Registration #8	2017-05-08	56.219 mi
Registration #9	2018-05-02	61.406 mi
Registration #10	2019-05-02	65.277 mi
Registration #11	2020-05-02	69.277 mi
Registration #12	2021-05-02	73.277 mi
Registration #13	2022-05-02	77.277 mi
Registration #14	2023-05-02	81.277 mi
Registration #15	2024-05-02	85.277 mi
Registration #16	2025-05-02	89.277 mi
Registration #17	2026-05-02	93.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1778 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	560100