



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	Black
Year of manufacture	2014
Top speed	108 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 2

Date	2022-06-24
Pictures	50
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-07-17
Pictures	50
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)



## MOT history

MOT expiry date	2024-08-17
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	14
Total items failed	8

MOT #10	2023-08-16 08:16
MOT test number	125258687361
Result	✓ Passed
Next expiry date	2024-08-17
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	T.P.M.S warning displayed

MOT #9	2022-08-18 14:41
MOT test number	960766118297
Result	✓ Passed

MOT #8	2022-02-04 11:30
MOT test number	998800008501
Result	✓ Passed

**MOT #7** 2021-01-25 12:58**MOT test number** 144591720856**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2020-01-24 11:15**MOT test number** 809600365018**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Tyre slightly damaged/cracking or perishing All 4 (5.2.3 (d) (ii))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #5** 2020-01-22 11:55**MOT test number** 696237560400**Result** ✗ Failed**Fail** Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Tyre slightly damaged/cracking or perishing All 4 (5.2.3 (d) (ii))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #4** 2019-01-17 15:32**MOT test number** 352505175474**Result** ✓ Passed**MOT #3** 2018-02-12 14:12**MOT test number** 979766279347**Result** ✓ Passed**MOT #2** 2017-07-07 14:54**MOT test number** 493571314269**Result** ✓ Passed**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**MOT #1** 2017-07-07 08:31**MOT test number** 349345000871**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**Fail** Nearside Side repeater has less than 50% of the light sources illuminating (1.4.A.2c)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
17 August 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	17 August 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-07-12
Last registration	2023-08-16
Complete history	<a href="#">See info</a>



Registration #1	2014-07-12	6 mi
Registration #2	2017-07-07	50.281 mi
Registration #3	2017-07-07	50.282 mi
Registration #4	2018-02-12	51.323 mi
Registration #5	2019-01-17	55.020 mi
Registration #6	2020-01-22	60.376 mi
Registration #7	2020-01-24	60.388 mi
Registration #8	2020-01-24	60.388 mi
Registration #9	2020-01-24	60.388 mi
Registration #10	2020-01-24	60.388 mi
Registration #11	2020-01-24	60.388 mi
Registration #12	2020-01-24	60.388 mi
Registration #13	2020-01-24	60.388 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4FDEZ280848