





General information

| Make | KIA |
|---------------------|-------------------|
| Model | RIO FIRST EDITION |
| Colour | Red |
| Year of manufacture | 2017 |
| Top speed | 118 mph |
| 0 - 60 mph | 9.8 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 118 BHP |
|-------------------------|---------------------|
| Max. torque | 171 Nm at 4.000 rpm |
| Engine capacity | 998 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 50.4 mpg |
| Consumption extra urban | 67.3 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 107 g/km |
| CO2 label | В |







Internet history

| Entry 2 | |
|---------------|-------------|
| Date | 2021-09-11 |
| Pictures | 24 |
| Listing price | View report |



source: heycar.co.uk

| Entry 1 | |
|---------------|-------------|
| Date | 2021-09-09 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk



MOT history

| MOT expiry date | 2025-03-15 |
|--------------------|------------|
| MOT pass rate | 83 % |
| MOT passed | 5 |
| Failed MOT tests | 1 |
| Total advice items | 7 |
| Total items failed | 1 |

| MOT #6 | 2024-02-27 10:36 |
|------------------|------------------|
| MOT test number | 179700139092 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-15 |

| MOT #5 | | 2023-03-08 14:36 |
|---|--|-----------------------|
| MOT test | number | 428266826303 |
| Result | | ✓ Passed |
| Advice | Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice Nearside Front Tyre slightly damaged/cracking or perishing Tyre slightly cracking (5.2.3 (d) (ii)) | | king (5.2.3 (d) (ii)) |
| Advice | Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |

| МОТ #4 | 2023-03-08 14:36 | |
|---|---|--|
| MOT test number | 199298316161 | |
| Result | × Failed | |
| Advice Nearside Front Brake disc worn, but not excessive | ly (1.1.14 (a) (i)) | |
| Advice Nearside Front Tyre slightly damaged/cracking or perishing Tyre slightly cracking (5.2.3 (d) (ii)) | | |
| Pass with rectification Front Windscreen wiper does no | t clear the windscreen effectively (3.4 (b) (ii)) | |
| Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | | |





| MOT #3 | 2022-03-01 13:57 | |
|--|------------------|--|
| MOT test number | 867084145010 | |
| Result | ✓ Passed | |
| | | |
| MOT #2 | 2021-03-09 11:21 | |
| MOT test number | 880639602189 | |
| Result | ✓ Passed | |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| | | |
| MOT #1 | 2020-03-12 12:36 | |
| MOT test number | 788570321038 | |
| Result | ✓ Passed | |



Tax & MOT check

| Tax due: 1 October 2024 | ✓ Taxed | Expires: 15 March 2025 | ✓ МОТ |
|-----------------------------------|------------|----------------------------------|------------------------|
| Tax status | | | Valid until 1 October |
| Days left | | | 154 |
| MOT expiry date | | | 15 March 2025 |
| Full MOT history | | | <u>See MOT history</u> |
| Tax calculation | | | |
| | | 40 | |

| Vehicle class | 48 |
|---|----------------|
| Band | В |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-----------|
| Date | FET I |
| Category | AMP |
| Туре | |
| Damage 2 | AMPLE |
| Damaye z | 6 C C D D |
| Date | 1. St |
| Category | AMP |
| Туре | |

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 = |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| *********** | |
| ******** | |
| | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this KIA had different number plates. | |
| Number of plates | 7 |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | More info > |





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2017-03-16 |
| Last registration | 2024-02-27 |
| Complete history | See info |



| Registration #1 | 2017-03-16 | 9 mi |
|-----------------|------------|------------|
| Registration #2 | 2020-03-12 | 9.152 mi |
| Registration #3 | 2021-03-09 | 11.523 mi |
| Registration #4 | | 11.777 esi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 est |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |

More info >





Car features

| S0225 | Air conditionin |
|--------|-----------------|
| S0295 | |
| S0482 | |
| \$0501 | |
| \$0566 | |
| \$0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 92% |
| Children | 84% |
| Pedestrian | 46% |
| Safety systems | 86% |
| Overall rating | 81% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1725 mm |
| Height | 1450 mm |
| Length | 4065 mm |
| Wheel base | 4065 mm |
| Kerb weight | 1248 kg |
| Max. allowed weight | 1620 kg |
| Additional information | |
| Fuel tank capacity | 45 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|--------------|
| Engine number | G3LCGP110467 |