





report date: 2024-03-29

General information

Make	HONDA
Model	FR-V I-CTDI ES
Colour	Black
Year of manufacture	2007
Top speed	118 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.204 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	Н



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1

Date	2021-11-04	
Pictures	1	
Listing price	<u>View report</u>	



source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT expiry date	2024-12-22
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	28
Total items failed	6

MOT #18	2023-12-12 13:34
MOT test number	227132283275
Result	✓ Passed
Next expiry date	2024-12-22
Advice Offside Rear Tyre worn close to legal limit/worn on edge near to cords (5.2.3 (e))	

MOT #17	2023-12-12 10:35
MOT test number	755418203410
Result	X Failed
Fail Offside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii)) Advice Offside Rear Tyre worn close to legal limit/worn on edge near to cords (5.2.3 (e))

MOT #16	2022-12-09 11:22
MOT test number	853124001187
Result	✓ Passed
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Front Brake pad(s) wearing thin very close to limit (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT test number

2022-12-09 10:44

MOT test number

212297155451

Result

Fail Windscreen washer not working (3.5 (a))

Advice Front Brake pad(s) wearing thin very close to limit (1.1.13 (a) (ii))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #14	2021-12-03 09:36
MOT test number	905681847541
Result	✓ Passed
MOT #13	2020-12-23 12:32
MOT test number	157304205832
Result	✓ Passed
Advice Front brake pads wearing thin	
Advice Rear drop links worn	
Advice Rear window washer not working	
Advice Rear wiper rubber split	

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #12 2020-12-23 12:32 **MOT** test number 281986180557 Result × Failed **Advice** Front brake pads wearing thin Advice Rear drop links worn Advice Rear window washer not working Advice Rear wiper rubber split Pass with rectification Nearside Front Service brake excessively binding (1.2.1 (f))

MOT test number

274855664553

Result

Advice

Nearside Front Tyre worn close to legal limit/worn on edge on inner edge of tread. (5.2.3 (e))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner edge of tread and 1.7mm (5.2.3 (e))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge of tread. (5.2.3 (e))

MOT #10	2018-07-13 09:24
MOT test number	862740192379
Result	✓ Passed

MOT #9

MOT test number

715011682207

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Rear windscreen washer not working

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front drop link worn

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #8		2016-06-30 09:27
MOT test	number	462094123287
Result		✓ Passed
Advice	Rear rear washer inoperative	
Advice	Offside Front Tyre tread worn on edges	

MOT #7	2015-07-03 12:09
MOT test number	289904985132
Result	✓ Passed
Notice Rear washers inoperative	

MOT #6		2014-07-23 12:33
MOT test number		567454604207
Result		✓ Passed
MOT #5		2014-07-23 12:33
MOT test number		867594904237
Result		X Failed
Pass with rectification	Offside Headlamp aim too low (1.8)	
Pass with rectification	Nearside Headlamp aim too low (1.8)	

2013-07-10 11:26
425321693122
✓ Passed
2012-07-13 10:02
835715892141
✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #2 2011-07-28 13:10 **MOT test number** 317199301417 Result ✓ Passed MOT #1 2010-09-13 12:54 **MOT test number** 484876650226 Result ✓ Passed **Notice** Child seat fitted to the middle rear seat Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) Notice Child seat fitted not allowing full inspection of adult belt Notice Nail in nearside rear tyre

CarCheck.co.uk page 7/14



MF57RUC report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	22 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



MF57RUC report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	
manana and a same and	

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	,
Current registration	NIE NIE NIE
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 11/14



MF57RUC report date: 2024-03-29

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-10
Last registration	2023-12-12
Complete history	See info



Registration #1	2007-09-10	23 mi
Registration #2	2010-09-13	21.159 mi
Registration #3	2011-07-28	23.544 mi
Registration #4	2012-07-13	28.902 mi
Registration #5	2013-07-10	36.560 mi
Registration #6	2014-07-23	49.084 mi
Registration #7	2015-07-03	55.139 mi
Registration #8	2016-06-30	64.785 mi
Registration #9	2017-07-20	71.112 mi
Posistration #10	2018-07-13	74.656 mi
Registration #10	2010-07-13	74.050 1111
Registration #11	2010-07-13	74.050 1111
-	2010-07-13	74.050 1111
Registration #11	2010-07-13	74.030 IIII
Registration #11 Registration #12	2010-07-13	74.030 III
Registration #11 Registration #12 Registration #13	2010-07-13	74.050 IIII
Registration #11 Registration #12 Registration #13 Registration #14	2010-07-13	74.050 IIII
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15	2010-07-13	74.050 III
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	2010-07-13	74.050 IIII
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17	2010-07-13	74.050 IIII

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1573 kg

Additional information

Fuel tank capacity	58 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Number of axles	2
Engine number	N22A12501639

CarCheck.co.uk page 14/14