



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | NISSAN |
| Model | NOTE VISIA |
| Colour | Black |
| Year of manufacture | 2010 |
| Top speed | 103 mph |
| 0 - 60 mph | 13.1 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 87 BHP |
| Max. torque | 128 Nm at 3.200 rpm |
| Engine capacity | 1.386 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 38.7 mpg |
| Consumption extra urban | 55.7 mpg |
| Consumption combined | 47.9 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |







Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-18 |
| Pictures | 8 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-12 |
| MOT pass rate | 65 % |
| MOT passed | 11 |
| Failed MOT tests | 6 |
| Total advice items | 18 |
| Total items failed | 4 |

| | |
|------------------|---|
| MOT #17 | 2023-07-11 12:01 |
| MOT test number | 949602423232 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-12 |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |

| | |
|-----------------|------------------|
| MOT #16 | 2022-06-27 08:55 |
| MOT test number | 558055455262 |
| Result | ✓ Passed |

| | |
|-----------------|---|
| MOT #15 | 2021-07-13 07:43 |
| MOT test number | 368621544988 |
| Result | ✓ Passed |
| Advice | Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |

| | |
|-----------------|---|
| MOT #14 | 2021-07-02 14:56 |
| MOT test number | 169233249342 |
| Result | ✗ Failed |
| MAJOR | Horn not working (7.7 (a) (ii)) |
| Advice | Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |

**MOT #13** 2020-08-20 08:48**MOT test number** 825122079174**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear exhaust has a slight leak**MOT #12** 2019-08-20 11:55**MOT test number** 440121369705**Result** ✓ Passed**MOT #11** 2019-08-20 08:52**MOT test number** 122834137399**Result** ✗ Failed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MAJOR** Horn not working (7.7 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #10** 2018-08-09 14:13**MOT test number** 939427781369**Result** ✓ Passed**MOT #9** 2018-08-09 11:07**MOT test number** 186283829524**Result** ✗ Failed**MAJOR** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Horn not working (7.7 (a) (ii))

**MOT #8** 2017-07-15 09:15**MOT test number** 839918635574**Result** ✓ Passed**MOT #7** 2016-06-01 12:51**MOT test number** 385437782155**Result** ✓ Passed**MOT #6** 2015-05-30 13:12**MOT test number** 257080555445**Result** ✓ Passed**MOT #5** 2015-05-30 13:12**MOT test number** 888880455129**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #4** 2014-05-30 16:42**MOT test number** 439890054192**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2014-05-30 13:49**MOT test number** 728110554117**Result** ✗ Failed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



| | |
|-----------------|---|
| MOT #2 | 2013-05-24 13:39 |
| MOT test number | 999714743148 |
| Result | ✓ Passed |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |

| | |
|-------------------------|---|
| MOT #1 | 2013-05-24 13:39 |
| MOT test number | 427164243151 |
| Result | ✗ Failed |
| Pass with rectification | Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) |
| Pass with rectification | Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
12 July 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 July |
| Days left | 63 |
| MOT expiry date | 12 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history


Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 10,000 |
| Auction value | £ 10,000 |
| Average private trade value | £ 10,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this NISSAN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-06-29 |
| Current registration | ***** |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2010-05-28 |
| Last registration | 2023-07-11 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2010-05-28 | 13 mi |
| Registration #2 | 2013-05-24 | 48.302 mi |
| Registration #3 | 2014-05-30 | 61.679 mi |
| Registration #4 | 2014-05-30 | 61.679 mi |
| Registration #5 | 2015-05-30 | 68.121 mi |
| Registration #6 | 2016-06-01 | 82.902 mi |
| Registration #7 | 2017-07-15 | 92.394 mi |
| Registration #8 | 2018-08-09 | 102.429 mi |
| Registration #9 | 2018-08-09 | 102.429 mi |
| Registration #10 | 2019-05-29 | 111.377 mi |
| Registration #11 | 2019-05-29 | 111.377 mi |
| Registration #12 | 2019-05-29 | 111.377 mi |
| Registration #13 | 2019-05-29 | 111.377 mi |
| Registration #14 | 2019-05-29 | 111.377 mi |
| Registration #15 | 2019-05-29 | 111.377 mi |
| Registration #16 | 2019-05-29 | 111.377 mi |
| Registration #17 | 2019-05-29 | 111.377 mi |

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1691 mm |
| Height | 1550 mm |
| Length | 4083 mm |
| Wheel base | 2600 mm |
| Kerb weight | 1092 kg |
| Max. allowed weight | 1546 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 46 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

Engine number

297604