





General information

Make	CITROEN
Model	BERLINGO 625 ENTERPRISE L1 BLUEHDI
Colour	White
Year of manufacture	2016
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	С





Internet history	
Entry 1	
Date	2021-01-29
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-12-04
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	19
Total items failed	1

MOT #8	2023-12-05 12:02
MOT test number	864091061643
Result	Passed
Next expiry date	2024-12-04
Minor Nearside Front Lower Windscreen damaged but not adversely affecting driver (i))	's view to osf (3.2 (a)
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1	.14 (a) (ii))

MOT #7	2022-11-10 10:21
MOT test	number 809298044431
Result	✓ Passed
Minor	Offside Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #6	2021-11-05 14:37
MOT test number	504989952407
Result	✓ Passed





MOT #5		2021-11-05 09:53
MOT test numbe	er	227442646317
Result		🗙 Failed
DANGEROUS	Tyre tread depth below requirements of 1.6mm all four (5.2.3 (e))	
DANGEROUS	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #4	2020-10-19 15:10
MOT test number	225571610205
Result	✓ Passed

MOT #3		2020-10-15 14:54
MOT test	number	431811508733
Result		🗙 Failed
MAJOR	Central Front Seat belt not functioning as intended (7.1.2 (c))	
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
MAJOR	Nearside Registration plate lamp likely to become detached (4.7.1 (c) (ii))	

MOT #2

мот	test	number
-----	------	--------

MOT test	number	127848461722
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Brake disc worn, but not excessively all four brake discs (1.1.14 (a) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

2019-11-08 13:36





MOT #1	2019-11-08 13:36
MOT test number	857247644760
Result	🗙 Failed
Pass with rectification Offside Headlamp not working on dipped beam (4.1.1 (a) (ii	i))
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice Brake disc worn, but not excessively all four brake discs (1.1.14 (a) (i))	



Tax & MOT check

X Untaxed Tax expired: 18 April 2024	MOT Expires: 4 December 2024
Tax status	Expired at 18 April 2024
Days left	10 days too late
MOT expiry date	4 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		Lamp
Туре		
Damage 2		AMPL
Date		· · ·
Category	1000000	AMPL
Туре		

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-11-08
Last registration	2023-12-05
Complete history	<u>See info</u>



Registration #1	2016-11-08	27 mi
Registration #2	2019-11-08	54.151 mi
Registration #3	2019-11-08	54.151 mi
Registration #4	2020-10-15	62.389 mi
Registration #5	2020-10-19	62.389 mi
Registration #6		11.777 esi
Registration #6 Registration #7		11.112 es
		01.000 est 01.000 est 01.000 est
Registration #7		01.000 est 01.000 est 01.000 est 01.000 est

More info >





Safety ratings

NCAP rating	
Adult	56%
Children	74%
Pedestrian	63%
Safety systems	48%
Overall rating	59%
Video	see crash video

Dimensions & weight

Width	2112 mm
Height	1801 mm
Length	4380 mm
Kerb weight	1309 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	JBHB3123865