



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D SE
Colour	Black
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg



LABEL UNKNOWN



Internet history

Entry 1	
Date	2021-06-29
Pictures	31
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #20	2023-07-04 13:31
MOT test number	992354391416
Result	✓ Passed
Next expiry date	2024-07-03
Advice	Tyre worn close to legal limit/worn on edge both front tyres worn on inside edges (5.2.3 (e))

MOT #19	2023-07-03 08:18
MOT test number	347639739331
Result	✗ Failed
Advice	Tyre worn close to legal limit/worn on edge both front tyres worn on inside edges (5.2.3 (e))
MAJOR	Exhaust has a major leak of exhaust gases back box blowing (6.1.2 (a))
MAJOR	Horn not working (7.7 (a))

MOT #18	2022-06-14 14:39
MOT test number	894960330345
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge on inside edge (5.2.3 (e))

MOT #17	2022-06-14 08:25
MOT test number	479245006135
Result	✗ Failed
MAJOR	Position lamp not working both front side lights (4.2.1 (a) (ii))
Advice	Service brake fluctuating, but not excessively both rear discs warped (1.2.1 (e))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
MAJOR	Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge on inside edge (5.2.3 (e))

**MOT #16** 2021-07-02 06:25**MOT test number** 210584671082**Result** ✓ Passed**MOT #15** 2021-06-30 13:20**MOT test number** 748535656526**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #14** 2021-03-15 13:50**MOT test number** 696158490677**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))**Advice** Offside Front Valve stem slightly damaged (5.2.3 (j))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))**Advice** Nearside Rear Valve stem slightly damaged (5.2.3 (j))**MOT #13** 2021-03-15 12:06**MOT test number** 748326996031**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))**Advice** Nearside Rear Valve stem slightly damaged (5.2.3 (j))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))**Advice** Offside Front Valve stem slightly damaged (5.2.3 (j))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

**MOT #12** 2020-03-14 11:57**MOT test number** 118934205434**Result** ✓ Passed**MOT #11** 2020-03-03 14:30**MOT test number** 862885110322**Result** ✗ Failed

MAJOR Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #10 2019-03-05 17:26**MOT test number** 316791142523**Result** ✓ Passed**MOT #9** 2019-03-05 13:22**MOT test number** 540465667038**Result** ✗ Failed

MAJOR Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #8 2018-04-06 15:43**MOT test number** 135505669457**Result** ✓ Passed

Advice Nearside Front Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #7 2017-04-03 15:52**MOT test number** 283197029289**Result** ✓ Passed

**MOT #6** 2017-04-03 15:52**MOT test number** 932176752396**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #5** 2016-04-01 09:00**MOT test number** 911740913865**Result** ✓ Passed**Advice** Child seats not strapped in at time of test**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2015-04-04 13:15**MOT test number** 885564895026**Result** ✓ Passed**MOT #3** 2015-04-02 17:53**MOT test number** 945862395025**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)



MOT #2	2014-02-28 10:47
MOT test number	309339954030
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components

MOT #1	2013-02-22 12:04
MOT test number	588673353086
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	LV10AAJ
Plate since	2019-03-28
Current registration	LV10AAJ
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2010-03-01
Last registration	2023-07-04
Complete history	See info



Registration #1	2010-03-01	27 mi
Registration #2	2013-02-22	25.755 mi
Registration #3	2014-02-28	33.949 mi
Registration #4	2015-04-02	42.172 mi
Registration #5	2015-04-04	42.172 mi
Registration #6	2016-04-01	56.212 mi
Registration #7	2017-04-03	72.481 mi
Registration #8	2017-04-03	72.481 mi
Registration #9	2018-04-06	85.765 mi
Registration #10	2019-03-05	94.616 mi
Registration #11	2019-03-05	94.616 mi
Registration #12	2019-03-05	94.616 mi
Registration #13	2019-03-05	94.616 mi
Registration #14	2019-03-05	94.616 mi
Registration #15	2019-03-05	94.616 mi
Registration #16	2019-03-05	94.616 mi
Registration #17	2019-03-05	94.616 mi
Registration #18	2019-03-05	94.616 mi
Registration #19	2019-03-05	94.616 mi
Registration #20	2019-03-05	94.616 mi
Registration #21	2019-03-05	94.616 mi
Registration #22	2019-03-05	94.616 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1450 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	768432