



PEUGEOT

MT06NGE

report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 VERVE E4
Colour	Silver
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg





Internet history

Entry 1

Date	2022-01-03
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #21	2023-06-29 11:59
MOT test number	821557179069
Result	✓ Passed
Next expiry date	2024-06-28
Advice	Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #20	2023-06-27 13:30
MOT test number	197822998748
Result	✗ Failed
Advice	Front Bumper mountings corroded but not likely to become detached (6.1.4 (a) (i))
MAJOR	Offside Rear Outer Seat belt anchorage prescribed area strength or continuity significantly reduced SILL (7.1.1 (a) (i))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #19	2022-06-28 09:52
MOT test number	141715218161
Result	✓ Passed
Advice	Nearside Front Inner Play in steering rack inner joint(s)

MOT #18	2021-07-29 10:42
MOT test number	366230394169
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Inner Steering linkage ball joint has slight play (2.1.3 (b) (i))

MOT #17	2020-07-15 12:42
MOT test number	729242055019
Result	✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Brake pipe corroded, covered in grease or other material all greased (1.1.11 (c))

**MOT #16**

2020-07-14 11:17

MOT test number

165139410958

Result**✗ Failed**

MAJOR Nearside Front Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength wing (5.3.6 (a) (i))

MAJOR Nearside Headlamp not working on dipped beam bulb missing (4.1.1 (a) (ii))

Advice Brake pipe corroded, covered in grease or other material all greased (1.1.11 (c))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MAJOR Nearside Headlamp not working on main beam bulb missing (4.1.1 (a) (ii))

MAJOR Nearside Side repeater light intensity significantly reduced (4.4.3 (a))

MOT #15

2019-07-04 10:32

MOT test number

378456001855

Result**✓ Passed**

Advice Slight corrosion to bulkhead

Advice Scatches in windscreen

Advice Rear axle and fuel tank corroded

MOT #14

2018-07-05 11:30

MOT test number

323771039676

Result**✓ Passed**

Advice Play in steering rack inner joint(s)

Advice Fuel tank strap corroded

Advice Nearside Rear Suspension component pin or bush slightly worn trailing arm (5.3.4 (a) (i))

Advice Both rear brake hoses ferrules corroded

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2018-07-05 11:30

MOT test number

500927719750

Result**✗ Failed****Advice** Nearside Rear Suspension component pin or bush slightly worn trailing arm (5.3.4 (a) (i))**Advice** Fuel tank strap corroded**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Play in steering rack inner joint(s)**Advice** Both rear brake hoses ferrules corroded**MOT #12**

2017-05-31 14:14

MOT test number

560749484207

Result**✓ Passed****Advice** Both rear tyres perishing**Advice** Fuel tank strap corroded**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Slight corrosion to nearside bulkhead

**MOT #11**

2017-05-30 10:00

MOT test number

460229020432

Result

✗ Failed

- Fail** Offside rear brake binding (3.7.B.1)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Fuel tank strap corroded
- Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Advice** Slight corrosion to nearside bulkhead
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Rear wheel bearing rough when rotated (2.6.1)
- Advice** Both rear tyres perishing

MOT #10

2016-06-03 10:06

MOT test number

785648537490

Result

✓ Passed

- Advice** Fuel tank strap corroded
- Advice** Nearside rear wheel bearing slightly noisy

MOT #9

2015-05-18 11:45

MOT test number

228168135125

Result

✓ Passed

- Notice** Oil leak
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #8	2015-05-15 09:43
MOT test number	335315035134
Result	✗ Failed
Notice	Oil leak
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Fail	Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
Fail	Front Brakes imbalanced across an axle (3.7.B.5b)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Under-trays fitted obscuring some underside components
Fail	Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
Fail	Rear Exhaust system not adequately supported (7.1.1)
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #7	2014-05-09 14:04
MOT test number	797269124179
Result	✓ Passed
Notice	Exhaust system deteriorated.

**MOT #6** 2014-05-09 11:01**MOT test number** 729829824195**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Rear Exhaust system not adequately supported (7.1.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Exhaust system deteriorated.**Fail** Nearside Headlamp aim too low (1.8)**MOT #5** 2013-05-17 12:09**MOT test number** 595957533193**Result** ✓ Passed**MOT #4** 2012-05-26 14:45**MOT test number** 925287042126**Result** ✓ Passed**MOT #3** 2011-06-13 16:04**MOT test number** 955394861149**Result** ✓ Passed**MOT #2** 2010-06-10 11:53**MOT test number** 214881160146**Result** ✓ Passed



MOT #1	2009-06-05 11:59
MOT test number	502506359168
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-06-16
Last registration	2023-06-29
Complete history	See info



Registration #1	2006-06-16	26 mi
Registration #2	2009-06-05	11.120 mi
Registration #3	2010-06-10	14.159 mi
Registration #4	2011-06-13	15.780 mi
Registration #5	2012-05-26	16.178 mi
Registration #6	2013-05-17	31.961 mi
Registration #7	2014-05-09	48.133 mi
Registration #8	2014-05-09	48.135 mi
Registration #9	2015-05-15	65.070 mi
Registration #10	2015-05-18	65.070 mi
Registration #11	2016-06-03	73.656 mi
Registration #12	2017-05-30	77.551 mi
Registration #13	2018-05-29	78.557 mi
Registration #14	2019-05-29	78.557 mi
Registration #15	2020-05-29	78.557 mi
Registration #16	2021-05-29	78.557 mi
Registration #17	2022-05-29	78.557 mi
Registration #18	2023-05-29	78.557 mi
Registration #19	2024-05-29	78.557 mi
Registration #20	2025-05-29	78.557 mi
Registration #21	2026-05-29	78.557 mi
Registration #22	2027-05-29	78.557 mi
Registration #23	2028-05-29	78.557 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	FST65298536