





report date: 2024-03-28

General information

Make	FORD
Model	MONDEO TITANIUM X 130
Colour	Silver
Year of manufacture	2008
Top speed	124 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	130 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.8 mpg
CO2 emission	189 g/km
CO2 label	J



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-06-09

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2022-01-14
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	31
Total items failed	10

MOT #14		2021-01-15 15:05
MOT test	number	341087472686
Result		✓ Passed
Next expi	ry date	2022-01-14
Advice	Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))		
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))	

	2021-01-12 14:57
number	119060447684
	🗙 Failed
Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
earside Rear Position lamp not working (4.2.1 (a) (ii))	
Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i)))
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Rear fog lamp not working (4.5.1 (a) (ii))	
Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i)) Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) earside Rear Position lamp not working (4.2.1 (a) (ii)) Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i) Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Efside Rear fog lamp not working (4.5.1 (a) (ii)) Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

CarCheck.co.uk page 3/13



MOT #12 2019-06-26 09:15

MOT test number 298548453981

MOT #11 2018-07-10 09:58

MOT test number 886453605304

Result

Passed

Advice Bonnet primary retaining device slightly deteriorated (3.1 (c))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Coil spring corroded both rear (5.3.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2017-07-19 09:53

MOT test number 950538618489

Advice Coil spring corroded both rear springs (2.4.C.1b)

MOT #9 2017-07-18 11:12

MOT test number 442593354865

Result X Failed

Fail Front brake disc in such a condition that it is seriously weakened both front discs inner disc face pitted and corroded. (3.5.1i)

Fail Rear Trailing arm rubber bush deteriorated resulting in excessive movement both sides. (2.4.G.2)

Advice Coil spring corroded both rear springs (2.4.C.1b)

MOT #8 2016-07-11 13:37

MOT test number 329443608812

Result
✓ Passed

Advice Front and rear subframes corroding.

CarCheck.co.uk page 4/13



MOT #5

PJ08JJK

report date: 2024-03-28

2014-07-21 12:33

MOT #7

MOT test number

696292005249

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Both front tyres worn on inner edges.

MOT #6 2015-07-21 15:53 **MOT** test number 608932005261 Result **X** Failed **Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b) Pass with rectification Nearside Headlamp aim too low (1.8) Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) Both front tyres worn on inner edges. Notice Pass with rectification Nearside Rear Rear position lamp(s) not working (1.1.A.3b) **Pass with rectification** Offside Headlamp aim too low (1.8)

MOT test number

Result

MOT #4

MOT test number

398532304269

Result

Pass with rectification

Nearside Front Headlamp aim too low (1.8)

Pass with rectification

Offside Front Headlamp aim too low (1.8)

CarCheck.co.uk page 5/13



MOT #3		2013-04-23 12:21
MOT test	number	649123613133
Result		✓ Passed
Notice	Rear tyres wearing low on inner edges	
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Wear/rust on rear brake disc faces	
Notice	Under-trays fitted obscuring some underside components	
Notice	Front and rear number plates deteriorating	

MOT #2		2012-05-23 10:52
MOT test	number	297254342129
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Vehicle's internal headlight adjuster altered to recheck lights	
Notice	Slight wear/rust on rear brake discs	
Notice	Under-trays fitted obscuring some underside components	
Notice	Items removed from driver's view prior to test	
Notice	Number plates starting to deteriorate	

MOT #1	2011-05-27 15:25
MOT test number	809727341124
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



X MOT

Tax expired: 1 June 2022

Expired: 14 January 2022

Tax status	Expired at 1 June 2022
Days left	697 days too late
MOT expiry date	14 January 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e when miscory	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NIE ALS UK
Plate since	*****
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2008-06-02
Last registration	2021-01-15
Complete history	See info



Registration #1	2008-06-02	10 mi
Registration #2	2011-05-27	55.657 mi
Registration #3	2012-05-23	75.000 mi
Registration #4	2013-04-23	92.241 mi
Registration #5	2014-07-21	100.742 mi
Registration #6	2015-07-21	108.240 mi
Registration #7	2016-07-11	114.715 mi
Registration #8		71.777 es
Registration #9		71.777 es
Registration #10		71.777 es
Registration #11		71.777 es
Registration #12		11.777 es
Registration #13		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 12/13



Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13