





report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 280 MWB SHR P/V 85
Colour	Grey
Year of manufacture	2011
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	250 Nm
Engine capacity	2.198 сс
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-10-03

Pictures 22

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2023-10-30
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	14
Total items failed	10

MOT #11		2022-10-31 16:08
MOT test	number	741369750451
Result		✓ Passed
Next exp	iry date	2023-10-30
Minor	Offside Side repeater lens defective which has no effect on emitted light (4	.4.1 (b) (i))
Advice	Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))	
Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))		
Advice	Offside front tyre slightly worn on outer edge.	

CarCheck.co.uk page 3/13



MOT #10 2022-10-29 13:05

MOT test number 684467405233

Result X Failed

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

Advice Offside front tyre slightly worn on outer edge.

Fail Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

Advice Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

Fail Nearside Front Service brake excessively fluctuating (1.2.1 (e))

Fail Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #9 2021-10-02 15:07

MOT test number 119618308665

Result / Passed

Advice Front Tyre worn close to legal limit/worn on edge offside and nearside (5.2.3 (e))

Advice Offside and nearside front suspension lower arms bush slightly worn.

MOT #8 2020-11-03 13:53

MOT test number 223105105263

Result \(\sqrt{Passed} \)

Advice Offside and nearside front suspension lower arms bush slightly deteriorated.

CarCheck.co.uk page 4/13



MOT #7 2019-10-29 12:08 640656552294 **MOT** test number Result ✓ Passed **MOT #6** 2018-10-27 13:57 **MOT** test number 522186850830 ✓ Passed Result **MOT** #5 2017-10-29 16:45 822994004873 **MOT** test number Result ✓ Passed **Advice** Offside Rear Nail in tyre

MOT #4

MOT test number

Result

Advice Offside Front Play in steering rack inner joint(s)

MOT #3

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Exhaust emits an excessive level of metered smoke (7.4.B.3a)

CarCheck.co.uk page 5/13



MOT #1 2014-06-25 13:05

MOT test number 586946174147

Result ✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check





31 August 2023	30 October 2023
Tax status	Expired at 31 August 2023
Days left	241 days too late
MOT expiry date	30 October 2023
Full MOT history	See MOT history

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



Extra FORD salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e which misterly	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	OK SIES
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-07-29
Last registration	2022-10-31
Complete history	See info



Registration #1	2011-07-29	19 mi
Registration #2	2014-06-25	65.015 mi
Registration #3	2015-06-25	75.762 mi
Registration #4	2015-06-26	75.810 mi
Registration #5	2016-08-06	84.741 mi
Registration #6	2017-10-29	94.928 mi
Registration #7	2018-10-27	106.881 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		11.777 mi
Registration #12		0.00 44
Registration #13		

More info >

CarCheck.co.uk page 12/13



Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Dimensions & weight

Width	2360 mm
Height	2532 mm
Length	5230 mm
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	BY63554

CarCheck.co.uk page 13/13