






report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI
Colour	White
Year of manufacture	2011
Top speed	93 mph
0 - 60 mph	16.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	225 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	49.6 mpg



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-06-26

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-06
MOT pass rate	100 %
MOT passed	12
Failed MOT tests	0
Total advice items	12
Total items failed	0

MOT #12	2024-02-07 15:59	
MOT test number	858659207385	
Result	✓ Passed	
Next expiry date	2025-02-06	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))		

MOT #11	2023-05-30 07:37
MOT test number	491696361173
Result	✓ Passed
Advice Slight injector leak	
Minor Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a)	(i))
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #10	2022-06-01 15:34
MOT test number	876934469820
Result	✓ Passed
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	

CarCheck.co.uk page 3/12



MOT #9	2021-06-10 10:48
MOT #9	2021-06-10 10:48

MOT test number 935544799874

Result ✓ Passed

MOT #8 2020-08-20 08:12

MOT test number 844142273429

Result ✓ Passed

MOT #7 2019-08-20 08:52

MOT test number 956620874984

Result \(\sqrt{Passed} \)

MOT #6 2018-07-31 08:17

MOT test number 827984394132

Result ✓ Passed

MOT #5 2017-08-24 11:44

MOT test number 894494198280

MOT #4 2016-09-26 11:23

MOT test number 802012526745

Result \rightarrow Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #3 2015-10-23 09:19

MOT test number 743207372346

Result

Passed

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)

CarCheck.co.uk page 4/12



MOT test number

Result

Advice Offside Front Valve stem slightly damaged (4.1.D.1e)

Advice Front registration plate delaminated but not likely to be misread (6.3.1d)

MOT #1

MOT test number

S59222644096

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status

Days left

MOT expiry date

Full MOT history

Valid until 1 October

6 February 2025

See MOT history

CarCheck.co.uk page 6/12




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-03-01
Last registration	2024-02-07
Complete history	See info



Registration #1	2011-03-01	21 mi
Registration #2	2014-02-11	54.197 mi
Registration #3	2014-10-31	55.370 mi
Registration #4	2015-10-23	65.733 mi
Registration #5	2016-09-26	75.826 mi
Registration #6	2017-08-24	86.471 mi
Registration #7	2018-07-31	92.239 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2062 mm
Height	1836 mm
Length	4876 mm
Kerb weight	1475 kg

Additional information

CarCheck.co.uk page 12/12