





report date: 2024-03-29

General information

| Make | BMW |
|---------------------|-------------------|
| Model | 520 520D SE |
| Colour | Grey |
| Year of manufacture | 2011 |
| Top speed | 140 mph |
| 0 - 60 mph | 8.1 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| Power | 181 BHP |
|-------------------------|---------------------|
| Max. torque | 380 Nm at 1.900 rpm |
| Engine capacity | 1.995 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 44.1 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 54.3 mpg |
| CO2 emission | 137 g/km |
| CO2 label | Е |



CarCheck.co.uk page 1/13



report date: 2024-03-29


Internet history

Entry 1

Date 2021-05-24

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



2022 00 26 11 41

report date: 2024-03-29

MOT history

| MOT expiry date | 2024-10-04 |
|--------------------|------------|
| MOT pass rate | 71 % |
| MOT passed | 10 |
| Failed MOT tests | 4 |
| Total advice items | 17 |
| Total items failed | 8 |

| MOT #14 | 2023-10-04 11:02 |
|------------------|------------------|
| MOT test number | 300372064056 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-04 |

| MOT #: | 2023-0 | 09-26 11:41 |
|--------|--|-----------------|
| MOT te | est number 767 | 619937108 |
| Result | | X Failed |
| Fail | Offside Front Suspension arm ball joint excessively worn arm that the shock bolts on to (5.3 | i.4 (a) (i)) |
| Fail | Oil leaking excessively from engine (8.4.1 (a) (i)) | |
| Fail | Nearside Front Position lamp not working (4.2.1 (a) (ii)) | |

CarCheck.co.uk page 3/13



report date: 2024-03-29

2022-10-05 09:02 **MOT #12** 271146758285 **MOT** test number Result ✓ Passed **Advice** Rear Prop shaft flexible coupling slightly deteriorated (6.1.7 (d) (i)) Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Advice Offside Front Suspension arm ball joint has slight play lower rear arm (5.3.4 (a) (i)) Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Front Suspension arm ball joint has slight play lower rear arm (5.3.4 (a) (i)) Advice Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

| MOT #11 | 2021-08-31 11:20 |
|--|------------------|
| MOT test number | 870043667841 |
| Result | ✓ Passed |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #10 | 2020-09-10 10:56 |
|-----------------|------------------|
| MOT test number | 799636445739 |
| Result | ✓ Passed |

| MOT #9 | 2020-09-02 14:14 |
|--|------------------|
| MOT test number | 214276925893 |
| Result | X Failed |
| Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) | |

CarCheck.co.uk page 4/13



MOT test number

FG11UBH

report date: 2024-03-29

426803947720

 MOT #8
 2019-07-09 15:27

 MOT test number
 366853920138

 Result
 ✓ Passed

 Advice
 Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT test number

638712422045

Result

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #6

MOT test number

Result

Advice (5.2.3 (e))

Passed

MOT #5

MOT test number

Result

MOT #4

2017-07-13 13:08

709185455938

√ Passed

Advice Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #3 2016-05-18 13:27
MOT test number 824186351062

Result × Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2015-03-30 11:06

MOT test number 808059585044

Result
✓ Passed

Advice Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

Advice Offside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

MOT #1 2014-03-26 10:50

MOT test number 597915384070

Result \rightarrow Passed

CarCheck.co.uk page 6/13



FG11UBH report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 January |
|------------------|-----------------------|
| Days left | 247 |
| MOT expiry date | 4 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| | |



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

| For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report | |
|---|--|
| | |
| ********* | |
| | |
| ************ | |
| | |
| ********* | |
| | |
| ************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this BMW had different number plates. | |
| Number of plates | |
| Current registration | UK UK |
| Plate since | |
| Current registration | NK SIN |
| Plate since | |
| | More info > |

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 16 |
| First mileage registration | 2011-04-19 |
| Last registration | 2023-10-04 |
| Complete history | See info |



| Registration #1 | 2011-04-19 | 20 mi |
|------------------|------------|-----------|
| Registration #2 | 2014-03-26 | 29.167 mi |
| Registration #3 | 2015-03-30 | 35.940 mi |
| Registration #4 | 2016-05-18 | 44.130 mi |
| Registration #5 | 2016-05-19 | 44.148 mi |
| Registration #6 | 2017-07-13 | 71.430 mi |
| Registration #7 | 2018-06-28 | 81.974 mi |
| Registration #8 | 2019-07-09 | 97.247 mi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 0.00 44 |
| Registration #13 | | 11.777 es |
| Registration #14 | | 0.00 44 |
| Registration #15 | | 11.777 mi |
| Registration #16 | | H 777 es |

More info >

CarCheck.co.uk page 12/13



FG11UBH report date: 2024-03-29

Car features

| The BMW factory car options list is only available in the premium report. | | | |
|---|------------------|--|--|
| S0225 | Air conditioning | | |
| S0295 | | | |
| S0482 | | | |
| S0501 | | | |
| S0566 | | | |
| S0567 | | | |

View the complete BMW factory list for this vehicle <u>here</u>.

More info >

Safety ratings

S0569

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 95% |
| Children | 83% |
| Pedestrian | 78% |
| Safety systems | 100% |
| Overall rating | 90% |
| Video | see crash video |



Dimensions & weight

| Width | 1860 mm |
|---------------------|---------|
| Height | 1475 mm |
| Length | 4899 mm |
| Wheel base | 1558 mm |
| Kerb weight | 1625 kg |
| Max. allowed weight | 2235 kg |

Additional information

| Fuel tank capacity | 70 | |
|-----------------------------------|------------------|-----------|
| Fuel delivery | Direct Injection | |
| Number of doors | 4 | |
| Number of seats CarCheck.co.uk | 5 p | age 13/13 |

Number of axles 2

Engine number 78497755