



report date: 2024-03-29

General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Red
Year of manufacture	2009
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





MOT history

MOT expiry date	2024-06-11
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	58
Total items failed	6

MOT #19	2023-06-12 13:15
MOT test number	960695761793
Result	✓ Passed
Next expiry date	2024-06-11

MOT #18	2023-06-09 10:18
MOT test number	349280977296
Result	✗ Failed
MAJOR Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
MAJOR Nearside Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))	
DANGEROUS Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
MAJOR Nearside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))	

MOT #17	2022-06-10 07:02
MOT test number	755901761940
Result	✓ Passed
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	

**MOT #16**

2022-06-10 07:02

MOT test number

725294281516

Result**✗ Failed****Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Pass with rectification** Nearside Front Windscreen wiper blade missing (3.4 (b) (ii))**Pass with rectification** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**MOT #15**

2021-12-16 10:36

MOT test number

552171607800

Result**✓ Passed****MOT #14**

2021-01-04 14:52

MOT test number

138610621879

Result**✓ Passed****Minor** Headlamp lens slightly defective Both (4.1.1 (b) (i))

**MOT #13**

2020-12-14 14:56

MOT test number

939598025912

Result**✗ Failed****MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Outer edge devoid of tread (5.2.3 (e))**MAJOR** Brake pedal has insufficient reserve travel (1.1.2 (a))**MOT #12**

2019-11-22 14:43

MOT test number

192776149473

Result**✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))**MOT #11**

2019-11-22 14:43

MOT test number

874076977401

Result**✗ Failed****Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))



MOT #10	2018-11-30 16:21
MOT test number	899761725635
Result	✓ Passed
Advice	Clutch worn
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear light lens damaged
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #9	2018-11-30 14:39
MOT test number	147259396921
Result	✗ Failed
MAJOR	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Rear light lens damaged
MAJOR	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Clutch worn

**MOT #8**

2017-11-23 13:58

MOT test number

532095083397

Result

✓ Passed

Advice Nearside Front Tyre worn close to the legal limit Outer edge (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Light lens damaged, but not showing white light**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7**

2016-12-17 15:41

MOT test number

117644683707

Result

✓ Passed

Advice Front number plate damaged**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Offside Rear bumper damaged**Advice** Offside Rear light cluster damaged

**MOT #6** 2016-12-17 09:41**MOT test number** 255400992888**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Offside Front Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear light cluster damaged**Advice** Front number plate damaged**Advice** Nearside Front Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Offside Rear bumper damaged**MOT #5** 2015-12-15 13:54**MOT test number** 682797622490**Result** ✓ Passed**MOT #4** 2014-12-20 10:42**MOT test number** 987354554396**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-12-18 09:20**MOT test number** 787282353313**Result** ✓ Passed



MOT #2	2013-12-18 09:20
MOT test number	445442453472
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too high (1.8)

MOT #1	2012-11-29 13:11
MOT test number	508544832360
Result	✓ Passed
Notice	Vehicle's internal headlight adjuster altered to recheck lights
Notice	Slight noise from offside front wheel bearing not rough at present
Notice	Front wiperblades poor/ dirty but still clearing windscreen



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✓
MOT

Expires:
11 June 2024

Tax status	Valid until 1 May
Days left	2
MOT expiry date	11 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-11-27
Last registration	2023-06-12
Complete history	See info



Registration #1	2009-11-27	17 mi
Registration #2	2012-11-29	24.646 mi
Registration #3	2013-12-18	35.633 mi
Registration #4	2014-12-20	43.740 mi
Registration #5	2015-12-15	51.456 mi
Registration #6	2016-12-17	55.187 mi
Registration #7	2016-12-17	55.187 mi
Registration #8	2017-11-23	63.260 mi
Registration #9	2018-11-30	68.336 mi
Registration #10	2018-11-30	68.336 mi
Registration #11	2019-06-20	75.277 mi
Registration #12	2019-06-20	75.277 mi
Registration #13	2019-06-20	75.277 mi
Registration #14	2019-06-20	75.277 mi
Registration #15	2019-06-20	75.277 mi
Registration #16	2019-06-20	75.277 mi
Registration #17	2019-06-20	75.277 mi
Registration #18	2019-06-20	75.277 mi
Registration #19	2019-06-20	75.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	107462