



RENAULT



report date: 2024-03-28

General information

| | |
|---------------------|--------------------------|
| Make | RENAULT |
| Model | CAPTUR DYNAMIQUE NAV DCI |
| Colour | Cream |
| Year of manufacture | 2015 |
| Top speed | 106 mph |
| 0 - 60 mph | 13.1 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 90 BHP |
| Max. torque | 220 Nm at 1.750 rpm |
| Engine capacity | 1.461 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 70.6 mpg |
| Consumption extra urban | 83.1 mpg |
| Consumption combined | 78.5 mpg |
| CO2 emission | 95 g/km |
| CO2 label | A |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-04 |
| Pictures | 10 |
| Listing price | View report |



source: autoonline.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-03-16 |
| MOT pass rate | 67 % |
| MOT passed | 6 |
| Failed MOT tests | 3 |
| Total advice items | 26 |
| Total items failed | 5 |

| | |
|------------------|---|
| MOT #9 | 2024-03-04 17:34 |
| MOT test number | 297119796566 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-16 |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

| | |
|-----------------|---|
| MOT #8 | 2024-03-04 12:39 |
| MOT test number | 846540936951 |
| Result | ✗ Failed |
| Fail | Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Rear heatshield insecure |
| Fail | Offside Rear Service brake excessively binding (1.2.1 (f)) |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) |

**MOT #7** 2023-03-14 10:23**MOT test number** 161667364055**Result** ✓ Passed

- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Parking brake travel long
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii))

MOT #6 2022-03-16 11:48**MOT test number** 887875771839**Result** ✓ Passed

- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))
- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))

MOT #5 2022-03-15 14:04**MOT test number** 523541734862**Result** ✗ Failed

- Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))

**MOT #4** 2021-03-17 11:07**MOT test number** 715035815135**Result** ✓ Passed**MOT #3** 2020-01-18 13:57**MOT test number** 867441986148**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2018-11-07 12:40**MOT test number** 707151431506**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2018-11-07 12:40**MOT test number** 115399882516**Result** ✗ Failed**Pass with rectification** Front Headlamp aim too low BOTH (4.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
16 March 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 338 |
| MOT expiry date | 16 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this RENAULT had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2019-09-29 |
| Current registration | |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 11 |
| First mileage registration | 2015-11-06 |
| Last registration | 2024-03-04 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2015-11-06 | 27 mi |
| Registration #2 | 2018-11-07 | 59.525 mi |
| Registration #3 | 2018-11-07 | 59.525 mi |
| Registration #4 | 2020-01-18 | 68.995 mi |
| Registration #5 | 2021-03-17 | 73.884 mi |
| Registration #6 | | |
| Registration #7 | | |
| Registration #8 | | |
| Registration #9 | | |
| Registration #10 | | |
| Registration #11 | | |

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 88% |
| Children | 79% |
| Pedestrian | 61% |
| Safety systems | 81% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1778 mm |
| Height | 1566 mm |
| Length | 4122 mm |
| Wheel base | 2606 mm |
| Kerb weight | 1178 kg |
| Max. allowed weight | 1727 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 45 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | D005801 |