





## General information

Make	RENAULT
Model	MASTER LL35 BUSINESS DCI P/C
Colour	White
Year of manufacture	2017
Top speed	92 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	130 BHP	0 < 101 A
Max. torque	310 Nm at 1.500 rpm	101 - 120 <sup>B</sup>
Engine capacity	2.298 сс	
Cylinders	4	141 - 165 F
Fuel type	Diesel	166 - 185 H
Consumption city	1.0 mpg	186 - 225 J
Consumption extra urban	1.0 mpg	225+ L
Consumption combined	35.8 mpg	
CO2 emission	207 g/km	
CO2 label	К	





# Internet history

Entry	1

Date Pictures 2021-08-15

50

Listing price

View report



source: cargurus.co.uk



### MOT history

MOT expiry date	2024-10-03
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	7
Total items failed	8

MOT #6		2023-10-04 15:38
MOT test	number	529944879627
Result		🗸 Passed
Next expiry date 2024-10-03		
Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))		
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #5		2023-10-04 15:38
MOT test number		961858167175
Result		🗙 Failed
Minor Offside Front Low	er Suspension arm ball joint dust cover severe	ely deteriorated (5.3.4 (b) (i))
Pass with rectification	Offside Front Position lamp not working (4.2.	1 (a) (ii))
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))		

МОТ #4	2022-10-04 15:54
MOT test number	621026770539
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	



WR17	ULC
report date:	2024-03-29

<b>MOT</b> #3	3	2021-06-18 13:38
MOT te	st number	849670400086
Result		✓ Passed
MOT #2	2	2020-04-01 13:41
MOT te	st number	611414639377
Result		✓ Passed
Advic	• Nearside Front Tyre worn close to legal limit/worn on edge badly on outer edge (5	5.2.3 (e))
MOT #3		2020-03-30 09:44
MOT te	st number	611084065690
Result		🗙 Failed
Fail	Hazard warning switch inoperative missing (4.4.2 (a) (ii))	
Fail	Nearside Rear Outline marker lamp showing white light to the rear lens broken (4.2.3	3 (a) (ii))
Fail	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)	)
Fail	Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))	
Fail	Nearside Front Obligatory mirror seriously damaged, affecting the rear view (3.3 (b)	(ii))
Fail	Nearside Rear Outline marker lamp not working (4.2.1 (a) (ii))	

Advice Nearside Front Tyre worn close to legal limit/worn on edge badly on outer edge (5.2.3 (e))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	✓ MOT Expires: 3 October 2024
Tax status	Valid until 1 October
Days left	155
MOT expiry date	3 October 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-





#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4 ARAPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

#### Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 11 711





### Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
**********	
********	
NUMBER OF TAXABLE	
**********	
********	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-03-31
Last registration	2023-10-04
Complete history	See info



Registration #1	2017-03-31	21 mi
Registration #2	2020-03-30	85.351 mi
Registration #3	2020-04-01	85.351 mi
Registration #4	2021-06-18	86.546 mi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		10.300 est





#### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Dimensions & weight

Width	2470 mm
Height	2264 mm
Length	6180 mm
Kerb weight	1669 kg
Max. allowed weight	3500 kg

# Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Number of axles	2
Engine number	C031680