



report date: 2024-03-28

General information

Make	NISSAN
Model	NOTE ACENTA PLUS 2
Colour	Black
Year of manufacture	2010
Top speed	108 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	160 Nm at 4.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.8 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-02-03
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2025-01-25
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	19
Total items failed	6

MOT #16	2024-01-26 11:01
MOT test number	430842122381
Result	✓ Passed
Next expiry date	2025-01-25
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15	2024-01-16 10:30
MOT test number	128449299554
Result	✗ Failed
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #14	2023-01-17 16:27
MOT test number	975546424839
Result	✓ Passed

**MOT #13** 2023-01-16 09:16**MOT test number** 581912370868**Result** ✗ Failed**Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Rear Engine mounting bracket damaged or deteriorated resulting in excessive movement (6.1.8 (a) (i))**MOT #12** 2021-12-17 09:41**MOT test number** 380009955810**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing inner and outer (5.2.3 (d) (ii))**Advice** Exhaust has a minor leak of exhaust gases exhaust backbox (6.1.2 (a))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing inner and outer (5.2.3 (d) (ii))**Advice** Offside Front Side repeater slightly discoloured (4.4.3 (a))**MOT #11** 2020-12-18 12:41**MOT test number** 733086643109**Result** ✓ Passed**MOT #10** 2020-08-05 08:38**MOT test number** 280021776717**Result** ✓ Passed

**MOT #9** 2019-08-15 08:25**MOT test number** 437008514383**Result** ✓ Passed**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #8** 2018-06-15 09:08**MOT test number** 614412447016**Result** ✓ Passed**Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #7** 2017-06-08 11:53**MOT test number** 950913926637**Result** ✓ Passed**Advice** Slight oil leak ?**MOT #6** 2016-06-01 08:59**MOT test number** 765353012754**Result** ✓ Passed**Advice** Nsf tyre on limit**MOT #5** 2015-06-22 15:30**MOT test number** 175763375194**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2015-06-22 10:52**MOT test number** 916023375121**Result** ✗ Failed**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front coil spring fractured (2.4.C.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-06-16 15:03**MOT test number** 238337564490**Result** ✓ Passed**MOT #2** 2014-06-13 12:52**MOT test number** 879004564120**Result** ✗ Failed**Fail** Nearside Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #1** 2013-06-04 11:01**MOT test number** 539035253151**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
25 January 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	25 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-09-01
Last registration	2024-01-26
Complete history	<a href="#">See info</a>



Registration #1	2010-09-01	26 mi
Registration #2	2013-06-04	10.160 mi
Registration #3	2014-06-13	16.199 mi
Registration #4	2014-06-16	16.199 mi
Registration #5	2015-06-22	24.871 mi
Registration #6	2015-06-22	24.871 mi
Registration #7	2016-06-01	32.721 mi
Registration #8	2017-06-08	39.272 mi
Registration #9	2018-06-15	46.221 mi
Registration #10	2019-06-22	53.170 mi
Registration #11	2020-06-22	60.119 mi
Registration #12	2021-06-22	67.068 mi
Registration #13	2022-06-22	74.017 mi
Registration #14	2023-06-22	80.966 mi
Registration #15	2024-01-26	87.915 mi
Registration #16	2024-01-26	87.915 mi
Registration #17	2024-01-26	87.915 mi
Registration #18	2024-01-26	87.915 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	


View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1780 mm
Height	1645 mm
Length	4525 mm
Wheel base	2765 mm
Kerb weight	1404 kg
Max. allowed weight	2072 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Engine number	13591B
---------------	--------