



RENAULT

AP60BXU

report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC SL27 DCI QUICKSHIFT
Colour	Blue
Year of manufacture	2011
Top speed	96 mph
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	115 BHP
Max. torque	290 Nm at 1.600 rpm
Engine capacity	1.996 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.4 mpg
Consumption extra urban	40.9 mpg
Consumption combined	38.1 mpg
CO2 emission	194 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-10-24
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-17
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	40
Total items failed	7

MOT #19	2023-10-18 12:29
MOT test number	886060211514
Result	✓ Passed
Next expiry date	2024-10-17
Advice	Front tyre walls cracking

MOT #18	2023-10-17 09:27
MOT test number	133623912138
Result	✗ Failed
Advice	Front tyre walls cracking
MAJOR	Windscreen washer not working (3.5 (a))

MOT #17	2022-10-18 09:34
MOT test number	407344024556
Result	✓ Passed
Advice	Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Brake pipe corroded, covered in grease or other material all brake pipes (1.1.11 (c))

**MOT #16**

2022-10-17 08:35

MOT test number

235665987221

Result**✗ Failed****Advice** Brake pipe corroded, covered in grease or other material all brake pipes (1.1.11 (c))**MAJOR** Rear Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Central Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #15**

2021-03-19 11:10

MOT test number

404100665244

Result**✓ Passed****Advice** No warning lights on dash time of test**Advice** Wheel trims fitted alround**MOT #14**

2021-03-19 11:10

MOT test number

363812002643

Result**✗ Failed****Pass with rectification** Nearside Front Side repeater not working connection (4.4.1 (a) (ii))**Advice** No warning lights on dash time of test**Advice** Wheel trims fitted alround**MOT #13**

2020-03-25 12:56

MOT test number

573613577897

Result**✓ Passed**

**MOT #12** 2020-03-24 12:13**MOT test number** 697875875787**Result** ✗ Failed

- MAJOR** Offside Front Headlamp levelling device inoperative (4.1.5 (a))
- MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #11 2019-04-16 13:59**MOT test number** 291326825187**Result** ✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material to caliper flexible hoses corroded (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material to caliper flexible hoses corroded (1.1.11 (c))
- Advice** Nearside Rear Tyre has thorn in side wall

MOT #10 2019-04-16 09:46**MOT test number** 495675926353**Result** ✗ Failed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material to caliper flexible hoses corroded (1.1.11 (c))
- Advice** Nearside Rear Tyre has thorn in side wall
- MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material to caliper flexible hoses corroded (1.1.11 (c))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #9**

2018-05-01 14:45

MOT test number

807509804409

Result

✓ Passed

- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement D bush (2.4.G.2)
- Advice** OS sliding door handle broken but the door can still be readily opened and closed
- Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement D bush (2.4.G.2)

MOT #8

2018-05-01 11:51

MOT test number

190566683970

Result

✗ Failed

- Advice** OS sliding door handle broken but the door can still be readily opened and closed
- Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement D bush (2.4.G.2)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside rear parking (secondary) brakes imbalanced (3.7.B.6b)
- Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement D bush (2.4.G.2)
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)

MOT #7

2017-04-28 15:42

MOT test number

697037523453

Result

✓ Passed

- Advice** Offside Rear Outer passenger door catch deteriorated but the door can still be readily opened and closed (6.2.B.2)

**MOT #6** 2017-04-28 09:31**MOT test number** 476904081470**Result** ✗ Failed

Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Central Rear stop light inop

Advice Offside Rear Outer passenger door catch deteriorated but the door can still be readily opened and closed (6.2.B.2)

MOT #5 2016-05-05 11:13**MOT test number** 341052561601**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Rear tyres perished

MOT #4 2015-04-30 14:30**MOT test number** 995780325149**Result** ✓ Passed

Advice Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

MOT #3 2015-04-29 11:17**MOT test number** 525149715153**Result** ✗ Failed

Fail Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Fail Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2 2014-05-06 17:09**MOT test number** 606296724101**Result** ✓ Passed



MOT #1	2013-12-16 10:38
MOT test number	138210453379
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
17 October 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	17 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	REDACTED
Plate since	2024-03-29
Current registration	REDACTED
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2011-01-27
Last registration	2023-10-18
Complete history	See info



Registration #1	2011-01-27	24 mi
Registration #2	2013-12-16	21.840 mi
Registration #3	2014-05-06	24.763 mi
Registration #4	2015-04-29	35.107 mi
Registration #5	2015-04-30	35.171 mi
Registration #6	2016-05-05	49.471 mi
Registration #7	2017-04-28	59.814 mi
Registration #8	2017-04-28	59.816 mi
Registration #9	2018-05-01	68.926 mi
Registration #10	2018-05-01	68.927 mi
Registration #11	2019-04-16	77.756 mi
Registration #12	2019-05-01	78.277 mi
Registration #13	2019-05-01	78.277 mi
Registration #14	2019-05-01	78.277 mi
Registration #15	2019-05-01	78.277 mi
Registration #16	2019-05-01	78.277 mi
Registration #17	2019-05-01	78.277 mi
Registration #18	2019-05-01	78.277 mi
Registration #19	2019-05-01	78.277 mi
Registration #20	2019-05-01	78.277 mi
Registration #21	2019-05-01	78.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1904 mm
Height	1957 mm
Length	4782 mm
Kerb weight	1918 kg
Max. allowed weight	2850 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	9
Engine number	C119297