



report date: 2024-03-29

General information

Make	FIAT
Model	PANDA ACTIVE
Colour	Yellow
Year of manufacture	2009
Top speed	93 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	54 BHP
Max. torque	87 Nm at 2.750 rpm
Engine capacity	1.108 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-06-29
Pictures	5
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-06-20
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-23
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	52
Total items failed	12

MOT #18	2023-09-21 08:36
---------	------------------

MOT test number	360703893784
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-09-23
------------------	------------

- Advice** Offside Rear Coil spring mounting corroded but not seriously weakened (5.3.1 (b) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Coil spring mounting corroded but not seriously weakened (5.3.1 (b) (i))
- Advice** Rear axle corroded
- Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #17**

2023-09-21 08:36

MOT test number

168165558966

Result**✗ Failed**

- Advice** Rear axle corroded
- Advice** Nearside Rear Coil spring mounting corroded but not seriously weakened (5.3.1 (b) (i))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring mounting corroded but not seriously weakened (5.3.1 (b) (i))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #16

2022-09-07 10:14

MOT test number

709215550651

Result**✓ Passed**

- Advice** Coil spring corroded AI 4 (5.3.1 (b) (i))
- Advice** Rear Shock absorbers has a slightly worn bush Both sides top bushes (5.3.2 (c))
- Advice** Nearside Brake cable damaged but not to excess Outer cable corroded and split (1.1.15 (a))

**MOT #15**

2021-09-03 10:23

MOT test number

783087523720

Result

✓ Passed

Advice Front Coil spring corroded Both (5.3.1 (b) (i))**Advice** Rear Suspension arm corroded but not seriously weakened Axle (5.3.3 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))**MOT #14**

2020-09-24 09:07

MOT test number

711371627908

Result

✓ Passed

Advice Rear Coil spring corroded Both (5.3.1 (b) (i))**Advice** Sump corroded

**MOT #13**

2020-09-04 10:09

MOT test number

838630384191

Result

✗ Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Heavily corroded (1.1.14 (a) (ii))

Fail Front Brakes imbalanced across an axle (1.2.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge On limit on inner edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Exhaust front bracket corroded and split, flex bracing up and rear box corroded

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge On limit on inner edge (5.2.3 (e))

Advice Coil spring corroded All 4 (5.3.1 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge On limit on inner edge (5.2.3 (e))

Advice Sump corroded

MOT #12

2019-03-21 09:56

MOT test number

590535687736

Result

✓ Passed

Advice Rear Exhaust box corroded

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Exhaust clamp and hanger corroded and split

Advice Sump starting to corrode

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Wearing on outer edge (5.2.3 (e))

Advice Coil spring corroded All 4 (5.3.1 (b) (i))

**MOT #11**

2018-04-11 10:05

MOT test number

345940019818

Result

✓ Passed

Advice Exhaust flex, clamps, and rear box corroded**Advice** Coil spring corroded All 4 (2.4.C.1b)**Advice** Nearside Front Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**MOT #10**

2018-04-10 11:55

MOT test number

726968622648

Result

✗ Failed

Fail Offside Front Lower Suspension arm rubber mounting deteriorated resulting in excessive movement rear bush (2.4.G.2)**Advice** Coil spring corroded All 4 (2.4.C.1b)**Fail** Offside Front Lower Ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)**Fail** Offside Front Lower Ball joint has excessive play (2.2.B.1f)**Advice** Nearside Front Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Exhaust flex, clamps, and rear box corroded**Fail** Nearside Front Lower Ball joint has excessive play (2.2.B.1f)**MOT #9**

2017-04-12 13:09

MOT test number

510707707716

Result

✓ Passed

MOT #8

2017-04-12 13:09

MOT test number

739294055446

Result

✗ Failed

Pass with rectification Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #7** 2016-03-16 12:06**MOT test number** 682660206866**Result** ✓ Passed**MOT #6** 2016-03-15 11:49**MOT test number** 246070776841**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2015-03-21 10:33**MOT test number** 439150785006**Result** ✓ Passed**Notice** N/s/r tyre cracking and distorting**Notice** Rear exhaust outer casing corroded**MOT #4** 2015-03-20 12:14**MOT test number** 185909675051**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Notice** N/s/r tyre cracking and distorting**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Rear exhaust outer casing corroded**MOT #3** 2014-02-04 12:36**MOT test number** 785575334016**Result** ✓ Passed**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Notice** Rear silencer deteriorated



MOT #2	2013-02-09 11:37
MOT test number	325730643023
Result	✓ Passed

MOT #1	2012-01-27 09:52
MOT test number	868997322037
Result	✓ Passed

Notice Rear silencer outer cover deteriorating



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
23 September 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	23 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-01-31
Last registration	2023-09-21
Complete history	See info



Registration #1	2009-01-31	27 mi
Registration #2	2012-01-27	26.921 mi
Registration #3	2013-02-09	32.679 mi
Registration #4	2014-02-04	38.799 mi
Registration #5	2015-03-20	47.024 mi
Registration #6	2015-03-21	47.033 mi
Registration #7	2016-03-15	56.101 mi
Registration #8	2016-03-16	56.101 mi
Registration #9	2017-04-12	66.734 mi
Registration #10	2017-04-12	66.734 mi
Registration #11	2018-04-10	74.577 mi
Registration #12	2019-05-20	82.320 mi
Registration #13	2020-06-10	90.063 mi
Registration #14	2021-07-01	97.806 mi
Registration #15	2022-08-01	105.549 mi
Registration #16	2023-09-21	113.292 mi
Registration #17	2024-01-01	121.035 mi
Registration #18	2024-02-01	128.778 mi
Registration #19	2024-03-01	136.521 mi
Registration #20	2024-04-01	144.264 mi
Registration #21	2024-05-01	152.007 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1578 mm
Height	1540 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	840 kg
Max. allowed weight	1255 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Number of axles	2
Engine number	4541941