



FE60YXN

report date: 2024-03-29

General information

Make	FORD
Model	MONDEO ZETEC TDCI 125
Colour	Silver
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg



**MOT history**

MOT #11	2020-11-13 16:45
MOT test number	316253049803
Result	✓ Passed
Next expiry date	2021-11-12

MOT #10	2019-10-17 10:19
MOT test number	490489581916
Result	✓ Passed

MOT #9	2018-11-10 08:27
MOT test number	731074923453
Result	✓ Passed

MOT #8	2017-11-01 13:59
MOT test number	610751041007
Result	✓ Passed

Advice Engine covers fitted

Advice Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

MOT #7	2017-11-01 13:59
MOT test number	427685444194
Result	✗ Failed

Pass with rectification Nearside Stop lamp not working (1.2.1b)

Advice Engine covers fitted

Pass with rectification Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

Pass with rectification Offside Stop lamp not working (1.2.1b)

**MOT #6** 2016-11-07 10:09**MOT test number** 167942940176**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Engine covers fitted**MOT #5** 2016-11-07 10:09**MOT test number** 691084560458**Result** ✗ Failed**Advice** Engine covers fitted**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (1.1.C.1a)**MOT #4** 2015-10-27 11:56**MOT test number** 650125801116**Result** ✓ Passed**Advice** Engine covers fitted obscuring view of some components in engine bay**Advice** Rear Exhaust has a minor leak of exhaust gases Silencer (7.1.2)**MOT #3** 2014-11-11 09:50**MOT test number** 209285814313**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2013-11-13 15:45
MOT test number	486837813497
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt

MOT #1	2013-11-13 13:27
MOT test number	479167513357
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Notice	Child seat fitted not allowing full inspection of adult belt



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	FE60YXN
Plate since	2019-09-29
Current registration	FE60YXN
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2010-09-24
Last registration	2020-11-13
Complete history	See info



Registration #1	2010-09-24	23 mi
Registration #2	2013-11-13	38.405 mi
Registration #3	2013-11-13	38.405 mi
Registration #4	2014-11-11	46.254 mi
Registration #5	2015-10-27	58.901 mi
Registration #6	2016-11-07	70.948 mi
Registration #7	2019-05-29	75.277 mi
Registration #8	2019-05-29	75.277 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1958 mm
Height	1429 mm
Length	4731 mm
Wheel base	2754 mm
Max. allowed weight	2155 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	AP49377