





report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VERSO VVT-I TR
Colour	Blue
Year of manufacture	2007
Top speed	121 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Semi-Automatic

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	44.1 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	ı



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-21

Pictures 38

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-08-20
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	18
Total items failed	7

MOT #19		2023-08-21 14:13
MOT test	number	300328059596
Result		✓ Passed
Next exp	iry date	2024-08-20
Minor	Registration plate lamp inoperative in the case of multiple lamps or ligh	nt sources (4.7.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1	.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing Damage to the	he tread (5.2.3 (d) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.	1.14 (a) (ii))

MOT #18	2022-04-12 14:44
MOT test number	358402368047
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #17	2021-03-30 09:	46
MOT test	number 1895538958	56
Result	✓ Passe	ed
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice (a) (ii))	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened Surface (1.1.14	
Advice (1.1.14 (a)	Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened Surface (ii))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #16 2020-03-18 11:06

MOT test number 755415527939

Result ✓ Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing In tread pattern. (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing in tread pattern. (5.2.3 (d) (ii))

MOT #15 2019-04-03 09:58

MOT test number 887564377227

Result \(\sqrt{Passed} \)

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #14 2018-04-05 06:45

MOT test number 599834179276

Result \(\sqrt{Passed} \)

Advice Front brake disc worn, pitted or scored, but not seriously weakened Both (3.5.1i)

Advice Rear Brake pipe slightly corroded Both (3.6.B.2c)

MOT #13 2017-05-16 10:01

MOT test number 173350318799

Result

Passed

Advice O/s and n/s rear brake pipes corroded

Advice Both front tyres / cracks on outer edges

CarCheck.co.uk page 4/13



Pass with rectification

BK07HLM

report date: 2024-03-28

MOT test number

Result

Advice
O/s and n/s rear brake pipes corroded

Pass with rectification
(8.2.2)

Advice
Both front tyres / cracks on outer edges

MOT #11

MOT test number

Result

MOT #10

MOT test number

2016-05-17 10:41

MOT test number

919539455518

Result

Pass with rectification
(8.2.2)

Offside Front Windscreen wiper does not clear the windscreen effectively split

 MOT #9
 2015-05-12 12:10

 MOT test number
 297002535452

 Result
 ✓ Passed

 MOT #8
 2015-05-12 12:10

 MOT test number
 708052835130

 Result
 X Failed

 MOT #7
 2014-05-19 12:06

 MOT test number
 128689234100

 Result
 ✓ Passed

Front registration plate deteriorated (6.3.1d)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #6	2013-05-21 10:33
MOT test number	548701743164
Result	✓ Passed
MOT #5	2012-05-08 10:12
MOT test number	655529422134
Result	✓ Passed
MOT #4	2012-05-08 10:12
MOT test number	469849222101
Result	★ Failed
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively
(8.2.2)	

MOT #3	2011-05-17 17:11
MOT test number	657557331170
Result	✓ Passed
MOT #2	2010-05-21 09:38
MOT test number	853491440194
Result	✓ Passed

Result	✓ Passed
MOT #1	2010 05 20 00.41
MOT #1	2010-05-20 09:41
MOT test number	773660740172
Result	★ Failed
Fail Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)	
Fail Nearside Rear Tyre has a bulge, caused by separation or partial failur	re of its structure (4.1.D.1b)

CarCheck.co.uk page 6/13



BK07HLM report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	20 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	NE UK
Plate since	
Current registration	NE ZIS
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-05-22
Last registration	2023-08-21
Complete history	See info



Registration #1	2007-05-22	12 mi
Registration #2	2010-05-20	30.369 mi
Registration #3	2010-05-21	30.387 mi
Registration #4	2011-05-17	38.924 mi
Registration #5	2012-05-08	45.910 mi
Registration #6	2013-05-21	53.129 mi
Registration #7	2014-05-19	60.848 mi
Registration #8	2015-05-12	68.222 mi
Registration #9	2016-05-17	73.934 mi
Registration #10	2016-05-17	73.934 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.177 ms

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13

Engine number

1ZZU896971