



RENAULT

LJ57BYY

report date: 2024-03-28

General information

| | |
|---------------------|--------------------|
| Make | RENAULT |
| Model | CLIO DYNAMIQUE VVT |
| Colour | Silver |
| Year of manufacture | - |
| Top speed | 116 mph |
| 0 - 60 mph | 12.2 seconds |
| Gearbox | 4 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 111 BHP |
| Max. torque | 151 Nm at 4.250 rpm |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 28.2 mpg |
| Consumption extra urban | 46.3 mpg |
| Consumption combined | 37.7 mpg |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-12 |
| Pictures | 80 |
| Listing price | View report |



source: autotrader.co.uk

**MOT history**

| | |
|-------------------------|------------------|
| MOT #16 | 2022-10-29 09:48 |
| MOT test number | 146036377650 |
| Result | ✓ Passed |
| Next expiry date | 2023-10-31 |

| | |
|------------------------|------------------|
| MOT #15 | 2021-10-08 14:21 |
| MOT test number | 940265255657 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #14 | 2020-10-12 09:39 |
| MOT test number | 793069379690 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #13 | 2019-11-01 15:40 |
| MOT test number | 869419117017 |
| Result | ✓ Passed |

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

| | |
|------------------------|------------------|
| MOT #12 | 2018-10-30 14:38 |
| MOT test number | 423286704480 |
| Result | ✓ Passed |

Advice Rear Inner Brake pad(s) wearing thin Both sides. (1.1.13 (a) (ii))

| | |
|------------------------|------------------|
| MOT #11 | 2018-10-30 14:38 |
| MOT test number | 335908064646 |
| Result | ✗ Failed |

Pass with rectification Offside Side repeater not working (4.4.1 (a) (ii))

Advice Rear Inner Brake pad(s) wearing thin Both sides. (1.1.13 (a) (ii))

Pass with rectification Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #10** 2017-10-30 14:05**MOT test number** 761762602416**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit Bald on outer edge.. 185/60 R15 88H (4.1.E.1)**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Nearside Outer Sill has been repaired with thick filler!**MOT #9** 2016-10-28 08:54**MOT test number** 272393387101**Result** ✓ Passed**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #8** 2015-10-07 10:01**MOT test number** 720582239808**Result** ✓ Passed**MOT #7** 2015-10-07 10:01**MOT test number** 810006007530**Result** ✗ Failed**Pass with rectification** Front registration plate deteriorated (6.3.1d)**MOT #6** 2014-10-03 13:21**MOT test number** 269926274212**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2014-10-03 13:21**MOT test number** 687476974213**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Windscreen wiper blade insecure (8.2.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2013-10-23 15:47**MOT test number** 308626293489**Result** ✓ Passed**Notice** Spare tyre defective**MOT #3** 2012-10-30 14:27**MOT test number** 447704602321**Result** ✓ Passed**MOT #2** 2011-10-21 14:29**MOT test number** 387284391498**Result** ✓ Passed**MOT #1** 2010-09-27 12:10**MOT test number** 111310170278**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | | |
|-------|------|----|
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |

More info >

Plate changes

See in this check if this RENAULT had different number plates.

| | |
|----------------------|-----------------|
| Number of plates | 1 |
| Current registration | REDACTED |
| Plate since | 2019-01-01 |
| Current registration | REDACTED |
| Plate since | 2019-01-01 |

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2007-09-28 |
| Last registration | 2022-10-29 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2007-09-28 | 11 mi |
| Registration #2 | 2010-09-27 | 13.086 mi |
| Registration #3 | 2011-10-21 | 17.124 mi |
| Registration #4 | 2012-10-30 | 20.807 mi |
| Registration #5 | 2013-10-23 | 24.630 mi |
| Registration #6 | 2014-10-03 | 28.409 mi |
| Registration #7 | 2015-10-07 | 31.956 mi |
| Registration #8 | 2015-10-07 | 31.956 mi |
| Registration #9 | 2016-10-28 | 33.903 mi |
| Registration #10 | 2016-10-28 | 35.850 mi |
| Registration #11 | 2016-10-28 | 37.797 mi |
| Registration #12 | 2016-10-28 | 39.744 mi |
| Registration #13 | 2016-10-28 | 41.691 mi |
| Registration #14 | 2016-10-28 | 43.638 mi |
| Registration #15 | 2016-10-28 | 45.585 mi |
| Registration #16 | 2016-10-28 | 47.532 mi |
| Registration #17 | 2016-10-28 | 49.479 mi |

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2025 mm |
| Height | 1496 mm |
| Length | 3986 mm |
| Wheel base | 2575 mm |
| Kerb weight | 1190 kg |
| Max. allowed weight | 1675 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|---------------|---------|
| Engine number | D014869 |
|---------------|---------|